COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

HJ70XGK

Ford Ranger Wildtrak 2.0 EcoBlue 213PS

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Present
Cap Id	44067
Cap Code	FORA20WILD7DTA4 6 L

Details

Location	Avonmouth	**Colour**	GREY	**CAP Below**	£7,975.00
Reg. date	06/11/2020	**VIN**	6FPPXXMJ2PLL31454	**Gearbox**	AUTOMATIC
Year	2020	**Body Style**	Pickup Double Cab	**Gears**	1
Mileage	80,014 Miles Not Warranted	**MOT Due**	14/01/2027	**Axle Combi**	4x4
Fuel Type	DIESEL	**CAP Clean**	£11,350.00		
GVW	3270kg	**CAP Average**	£9,950.00		

AD BLUE, TOW BAR, ROOF RACK, ALLOY WHEELS, E/MIRRORS, HEATED WINDSCREEN

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	

Features

- Bluetooth connection
- Park assist camera
- USB/iPod interface
- Passenger airbag
- Cruise control
- Rear parking sensor
- Air conditioning
- Central locking
- Front parking sensor
- Digital radio
- Front electric windows
- Leather seat trim
- Navigation system
- Radio/CD
- Drivers airbag

Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Wing nsf
Dented
With Paint Damage



3: Wing nsf
Scratched
Over 25mm Thru Paint



4: Door nsf
Chipped
1 To 5



5: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



6: Qtr Panel nsr
Dented
Between 10mm + 30mm



7: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



8: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



9: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



10: Bumper Rear
Scratched
25 to 100mm Thru Paint



11: Tailgate
Scratched
Over 25mm Thru Paint



12: Tailgate
Scratched
Over 25mm Thru Paint



13: Qtr Panel osr
Chipped
1 To 5



14: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



15: Qtr Panel osr
Chipped
Multiple Chips



16: Qtr Panel osr
Scratched
Over 25mm Thru Paint



17: Door osf
Chipped
Multiple Chips



18: Door osf
Chipped
1 To 5



19: Wing osf
Scratched
Over 25mm Thru Paint



20: Wing osf
Scratched
Over 25mm Thru Paint



21: Bumper Front
Scratched
25 to 100mm Thru Paint

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	-

Engine Runs	OK	No Excessive Smoking	OK
Brakes	OK		
Parking Brake	OK		
EML light illuminated	OK	DPF light illuminated	OK
Airbag light illuminated	OK		
ABS light illuminated	OK		