



Commercial Vehicle Auctions Ltd.

MX19DXE

CN: VF1VA000562549353

Photos



General Details

RENAULT MASTER LL35 BUSINESS 2.3 DCI 130PS

Vat Status: Commercial (plus Vat)

Mileage	180,800 miles	Miles Warranty	Yes
Colour	White	Fuel	Diesel
Transmission	Manual	Fuel Level	Red
Reg Date	12/08/2019	Engine Size	
Body Type			

Details

Engine No	Cab Type	Plated Weight	Doors
Body Length	Axle Combi	Steering Combi	Rear Susp
Gears	6 DFR	YOM	Runner? Yes/No
		2019	Yes



Valid MOT
Expires: 11/08/2025



V5 with CVA

Extras

Stereo:	Radio	Electric	2
Interior:	Cloth	Windows:	
Sat Nav:	No	Central Locking:	Yes
Air	Yes	Phone Kit:	No
Conditioning:		Metallic Paint:	No
Cruise Control	No		

Tyres & Wheels


Alloy	OSF	3mm-5mm
Steel ✓	Depth	mm
	NSF	3mm-5mm
	Depth	mm
	OSR	3mm-5mm
	Depth	mm
	NSR	3mm-5mm
	Depth	mm

Interior Condition

Carpets	Average
Upholstery	Average
Seats	Average
Odour	Average
Comments	


Service History

Service History	No
Stamps	



Damage Lines

Component	Condition	Severity	Repair
Sill os	Scratched	Over 25mm Thru Paint	Refinish
Bonnet	Dented	Over 30mm	Repair and Refinish
Door osf	Dented	With Paint Damage	Repair and Refinish
Qtr Panel osr	Dented	With Paint Damage	Repair and Refinish
Tailgate	Dented	With Paint Damage	Repair and Refinish
Qtr Panel nsr	Scratched	Over 25mm Thru Paint	Refinish
Door nsf	Dented	With Paint Damage	Repair and Refinish
Wing nsf	Dented	With Paint Damage	Repair and Refinish
Roof	Rusted	Over 5mm	Refinish



S2
Scratch/Paint defect 30-100mm
D2
Dent/damage 30-100mm
D3
Dent/damage 100mm +
R
Rust

Damage Assessment



Sill os

Scratched
Over
25mm
Thru Paint
Refinish



Bonnet

Dented
Over
30mm
Repair
and
Refinish



Door osf

Dented
With Paint
Damage
Repair
and
Refinish



Qtr Panel osr

Dented
With Paint
Damage
Repair
and
Refinish



Tailgate

Dented
With Paint
Damage
Repair
and
Refinish



Qtr Panel nsr

Scratched
Over
25mm
Thru Paint
Refinish



Door nsf

Dented
With Paint
Damage
Repair
and
Refinish



Wing nsf

Dented
With Paint
Damage
Repair
and
Refinish



Roof

Rusted
Over 5mm
Refinish

Comments

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.

The details within this inspection report are correct at point of vehicle arrival. Updates, errors and omissions will be highlighted by the CVA Auctions via catalogues, the website, entry forms or by the auctioneer.