

Carr Hil Industrial Estate Doncaster South Yorkshire DN4 8DE **Tel:** 01302 732600 **Email:** enquiries@cva-auctions.co.uk

Commercial Vehicle Auctions Ltd.



CN: VF7YCBNFB12S05560

<section-header>

General Details

CITROEN RELAY 35 ENTERPRISE 2.2 BLUEHDI 140PS

Vat Status: Commercial (plus Vat)

Mileage112,998 milesColourWhiteTransmissionManualReg Date25/03/2021Body TypeImage: Colour Col

Miles Warranty Fuel Fuel Level Engine Size

Diesel Quarter

Engine NoCab TypePlated WeightDoorsBody LengthAxle CombiSteering CombiRear SuspGears6DFR25/03/2021YOM2021Runner? Yes/NoYes



Details

No Valid MOT Expired: 05/04/2025



V5 with CVA

Extras		Tyres & Wh	neels		Interior Cond	dition	Service Histo	ry
Interior: Cloth Electric Sat Nav: Yes Windows: Air Yes Central Lock Conditioning: Phone Kit: Cruise Control No Metallic Pair	No	Alloy Steel √	OSF Depth NSF Depth OSR Depth NSR Depth	mm mm mm	Carpets Upholster Seats Odour Comment	Average Average	Service History Stamps	No

Photos





































Damage Lines

Component	Condition	Severity	Repair
Bumper Front	Dented	Over 30mm	Repair and Refinish
Door Mirror Assy nsf	Broken	Replace	Replace
Qtr Panel Arch Extension ns	Scuffed (Unpainted)	UpTo 100mm	Smart Repair
Bumper Rear	Cracked	Over 25mm	Replace
Panel Rear	Dented	Hail - Severe	Replace
Panel Rear	Dented	Over 30mm	Repair and Refinish
A Post os	Dented	Hail - Moderate	Repair and Refinish
Carpets Front	Torn	Over 10mm	Replace

Damage Assessment



Bumper Front Dented Over 30mm

Repair and Refinish

Bumper

Cracked

Rear

Over

25mm

Replace



Door Mirror Assy nsf Broken Needs Replaced Replace

Panel

Rear

Dented

Severe

Replace

Hail -



Qtr Panel Arch Extension ns Scuffed (Unpainted)

UpTo 100mm

Smart Repair

Panel Rear Dented

Over

30mm Repair

and Refinish



A Post os Dented Hail -Moderate Repair and Refinish



Carpets Front Torn Over 10mm Replace

Comments

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.

The details within this inspection report are correct at point of vehicle arrival. Updates, errors and omissions will be highlighted by the CVA Auctions via catalogues, the website, entry forms or by the auctioneer.