



Commercial Vehicle Auctions Ltd.

LB21JFE**CN: VF7YCBNFB12S21616**

Photos



General Details

CITROEN RELAY ENTERPRISE 35 2.2 BLUEHDI 140PS

Vat Status: Commercial (plus Vat)

Mileage	127,794 miles	Miles Warranty	No
Colour	White	Fuel	Diesel
Transmission	Manual	Fuel Level	Quarter
Reg Date	31/03/2021	Engine Size	
Body Type			

Details

Engine No	Cab Type	Plated Weight	Doors
Body Length	Axle Combi	Steering Combi	Rear Susp
Gears	6 DFR	YOM	Runner? Yes/No
	31/03/2021	2021	Yes



Valid MOT
Expires: 15/04/2025



V5 with CVA

Extras

Stereo:	Radio	Electric	2
Interior:	Cloth	Windows:	
Sat Nav:	No	Central	Yes
Air	Yes	Locking:	
Conditioning:		Phone	No
Cruise Control	Yes	Kit:	
		Metallic	No
		Paint:	
		Other:	Warning light on dash - emissions

Tyres & Wheels

Alloy	OSF Depth	mm
Steel ✓	NSF Depth	mm
	OSR Depth	mm
	NSR Depth	mm

Interior Condition


Carpets	Poor
Upholstery	Average
Seats	Average
Odour	Average
Comments	

Service History

Service History	No
Stamps	



Damage Lines			
Component	Condition	Severity	Repair
Bonnet	Chipped	1 To 5	Smart Repair
Door Mirror Assy nsf	Broken	Replace	Replace
Qtr Panel Trim ns	Missing	Replace	Replace
Qtr Panel nsr	Scratched	UpTo 25mm Not Thru Paint	Machine Polish
Panel Rear	Chipped	Over 5mm	Refinish
Panel Rear	Chipped	Multiple Chips	Refinish
D Post os	Chipped	Multiple Chips	Refinish
D Post os	Dented	Hail - Moderate	Repair and Refinish
A Post os	Dented	Hail - Moderate	Repair and Refinish
Carpets Front	Torn	Over 10mm	Replace

Damage Assessment					
	Bonnet Chipped 1 To 5 Smart Repair		Door Mirror Assy nsf Broken Needs Replaced Replace		Qtr Panel Trim ns Missing Needs Replaced Replace
	Qtr Panel nsr Scratched UpTo 25mm Not Thru Paint Machine Polish		Panel Rear Chipped Over 5mm Refinish		Panel Rear Chipped Multiple Chips Refinish
	D Post os Chipped Multiple Chips Refinish		D Post os Dented Hail - Moderate Repair and Refinish		A Post os Dented Hail - Moderate Repair and Refinish
	Carpets Front Torn Over 10mm Replace				

Comments

Warning light on dash - emissions

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.

The details within this inspection report are correct at point of vehicle arrival. Updates, errors and omissions will be highlighted by the CVA Auctions via catalogues, the website, entry forms or by the auctioneer.