



Commercial Vehicle Auctions Ltd.

DP19VVT

CN: XLRAEL1500L488429

Photos



General Details

DAF LF 180 EURO 6 7.5 TONNE

Vat Status: Commercial (plus Vat)

Mileage	200,777 km	Miles Warranty	
Colour	White	Fuel	Diesel
Transmission	Manual	Fuel Level	
Reg Date	27/06/2019	Engine Size	
Body Type			

Details

Engine No	Cab Type	Crew Cab	Plated Weight	Doors	
Body Length	Axle Combi	4x2	Steering Combi	Rear Susp	Spring
Gears	6 DFR	27/06/2019	YOM	2019	Runner? Yes/No
					Yes



Valid MOT
Expires: 30/09/2025



V5 with CVA

Extras



Stereo:	CD	Electric Windows:	2
Interior:	Cloth	Central Locking:	Yes
Sat Nav:	No	Phone Kit:	No
Air Conditioning:	No	Metallic Paint:	No
Cruise Control	Yes		

Interior Condition

Carpets	Good
Upholstery	Good
Seats	Poor
Odour	
Comments	

Service History

Service History	No
Stamps	






Damage Lines

Component	Condition	Severity	Repair
Panel Front	Scratched	Over 25mm Thru Paint	Refinish
Bumper Front	Scratched	Over 100mm Thru Paint	Refinish
Door nsf	Scratched	Over 25mm Thru Paint	Refinish
Qtr Panel nsr	Scratched	Over 25mm Thru Paint	Refinish
Qtr Panel osr	Scratched	Over 25mm Thru Paint	Refinish
Door osf	Scratched	Over 25mm Thru Paint	Refinish
Seat Base Cover osf	Torn	Over 3mm	Replace
Dash Warning Lights	Displayed	No Action	Report Only

Vehicle Splat



Splat Key

- S2**
Scratch/Paint defect 30-100mm
- S3**
Scratch/Paint defect 100m +

Damage Assessment



Panel Front

Scratched

Over 25mm Thru Paint

Refinish




Bumper Front

Scratched

Over 100mm Thru Paint

Refinish



Door nsf

Scratched

Over 25mm Thru Paint

Refinish



**Qtr Panel
nsr**

Scratched

Over
25mm
Thru Paint

Refinish



**Qtr Panel
osr**

Scratched

Over
25mm
Thru Paint

Refinish



Door osf

Scratched

Over
25mm
Thru Paint

Refinish



**Seat
Base
Cover
osf**

Torn

Over 3mm

Replace



**Dash
Warning
Lights**

Displayed

No Action

Report
Only

Comments

tpms DISPLAYED

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.

The details within this inspection report are correct at point of vehicle arrival. Updates, errors and omissions will be highlighted by the CVA Auctions via catalogues, the website, entry forms or by the auctioneer.