



# Commercial Vehicle Auctions Ltd.

MX69AUJ

CN: VF1VA000062549227

## Photos



## General Details

RENAULT MASTER LL35 2.3 DCI BUSINESS

Vat Status: Commercial (plus Vat)

|              |               |                |        |
|--------------|---------------|----------------|--------|
| Mileage      | 154,273 miles | Miles Warranty |        |
| Colour       | White         | Fuel           | Diesel |
| Transmission | Manual        | Fuel Level     |        |
| Reg Date     | 11/10/2019    | Engine Size    |        |
| Body Type    |               |                |        |

## Details

|             |            |                |                |
|-------------|------------|----------------|----------------|
| Engine No   | Cab Type   | Plated Weight  | Doors          |
| Body Length | Axle Combi | Steering Combi | Rear Susp      |
| Gears       | 6 DFR      | YOM            | Runner? Yes/No |
|             |            |                | Yes            |



Valid MOT  
Expires: 10/10/2025



No V5

## Extras

|                |       |            |           |
|----------------|-------|------------|-----------|
| Stereo:        | HDD   | Electric   | 2         |
| Interior:      | Cloth | Windows:   |           |
| Sat Nav:       | No    | Central    | Yes       |
| Air            | Yes   | Locking:   |           |
| Conditioning:  |       | Phone Kit: | BlueTooth |
| Cruise Control | Yes   | Metallic   | No        |
|                |       | Paint:     |           |

## Tyres & Wheels

|         |           |    |
|---------|-----------|----|
| Alloy   | OSF Depth | mm |
| Steel ✓ | NSF Depth | mm |
|         | OSR Depth | mm |
|         | NSR Depth | mm |

## Interior Condition

|            |      |
|------------|------|
| Carpets    | Poor |
| Upholstery | Good |
| Seats      | Good |
| Odour      | Good |
| Comments   |      |

## Service History

|                 |    |
|-----------------|----|
| Service History | No |
| Stamps          |    |






## Damage Lines

| Component           | Condition | Severity             | Repair              |
|---------------------|-----------|----------------------|---------------------|
| Bonnet              | Chipped   | Multiple Chips       | Refinish            |
| Wing nsf            | Dented    | Over 30% Of Panel    | Replace             |
| Door nsr            | Cracked   | Replace              | Replace             |
| Door osr            | Cracked   | Replace              | Replace             |
| Qtr Panel osr       | Scratched | Over 25mm Thru Paint | Refinish            |
| Wing osf            | Dented    | Over 30mm            | Repair and Refinish |
| Seat Base Cover osf | Holed     | Over 3mm             | Replace             |
| Dash Warning Lights | Displayed | No Action            | Report Only         |

## Vehicle Splat



## Splat Key


- S3**  
Scratch/Paint defect 100m +
- D3**  
Dent/damage 100mm +
- C2**  
Multiple Chips
- K**  
Crack/Torn

## Damage Assessment



### Bonnet

- Chipped
- Multiple Chips
- Refinish



### Wing nsf

- Dented
- Over 30% Of Panel
- Replace



### Door nsr

- Cracked
- Needs Replaced
- Replace




### Door osr

- Cracked
- Needs Replaced
- Replace



### Qtr Panel osr

- Scratched
- Over 25mm Thru Paint
- Refinish



### Wing osf

- Dented
- Over 30mm
- Repair and Refinish




Seat  
Base  
Cover  
osf

Holed

Over 3mm

Replace



Dash  
Warning  
Lights

Displayed

No Action

Report  
Only

Comments

eml displayed

**No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.**

The details within this inspection report are correct at point of vehicle arrival. Updates, errors and omissions will be highlighted by the CVA Auctions via catalogues, the website, entry forms or by the auctioneer.