



Commercial Vehicle Auctions Ltd.

PN66PLV

CN: XLRACM4300G104510

Photos



General Details

DAF CF 460 EURO 6

Vat Status: Commercial (plus Vat)

Mileage	408,664 km	Miles Warranty	
Colour	White	Fuel	Diesel
Transmission	Manual	Fuel Level	Red
Reg Date	03/11/2016	Engine Size	
Body Type			

Details

Engine No	Cab Type	Plated Weight	Doors
Body Length	Axle Combi	Steering Combi	Rear Susp
Gears	DFR	YOM	Runner? Yes/No
	03/11/2016	2016	Air Yes



Valid MOT
Expires: 31/01/2026



V5 with CVA

Extras




Stereo:	Radio	Electric Windows:	2
Interior:	Cloth	Central Locking:	Yes
Sat Nav:	Yes	Phone Kit:	No
Air Conditioning:	Yes	Metallic Paint:	No
Cruise Control	Yes		

Interior Condition

Carpets	Average
Upholstery	Average
Seats	Average
Odour	
Comments	

Service History

Service History	No
Stamps	






Damage Lines

Component	Condition	Severity	Repair
Door Moulding osf	Scuffed (Unpainted)	Over 100mm	Smart Repair
Wing nsf	Poor Previous Repair	Poor Paint	Refinish
Bumper Front	Scratched	Over 100mm Thru Paint	Refinish
Door osf	Dented	Between 10mm + 30mm	Smart Repair
Qtr Panel osr	Dented	With Paint Damage	Repair and Refinish
Tailgate	Rusted	Over 5mm	Refinish
Qtr Panel nsr	Dented	With Paint Damage	Repair and Refinish
Door nsf	Dented	Over 30mm	Repair and Refinish

Vehicle Splat



Splat Key

S3	Scratch/Paint defect 100m +
D2	Dent/damage 30-100mm
D3	Dent/damage 100mm +
PP	Poor Previous
SC	Scuff

Damage Assessment



Door Moulding osf

Scuffed (Unpainted)
Over 100mm
Smart Repair



Wing nsf

Poor Previous Repair
Poor Paint
Refinish



Bumper Front

Scratched
Over 100mm Thru Paint
Refinish



Door osf

Dented
Between 10mm + 30mm



Qtr Panel osr

Dented
With Paint Damage



Tailgate

Rusted
Over 5mm
Refinish



Smart
Repair



Repair
and
Refinish



**Qtr Panel
nsr**

Dented

With Paint
Damage

Repair
and
Refinish



Door nsf

Dented

Over
30mm

Repair
and
Refinish

Comments

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.

The details within this inspection report are correct at point of vehicle arrival. Updates, errors and omissions will be highlighted by the CVA Auctions via catalogues, the website, entry forms or by the auctioneer.