

Carr Hil Industrial Estate Doncaster South Yorkshire DN4 8DE Tel: 01302 732600 Email: enquiries@cva-auctions.co.uk

Commercial Vehicle Auctions Ltd.



CN: W1V9076352P254710

<section-header>

General Details

MERCEDES-BENZ SPRINTER 314 CDI Vat Status: Commercial (plus Vat)

 Mileage
 178,469 miles

 Colour
 White

 Transmission
 Auto

 Reg Date
 29/07/2020

 Body Type
 Colour

Miles Warranty Fuel Fuel Level Engine Size

Diesel

Details							
Engine No	Cab Type		Plated Weight		Doors Rear Susp		
Body Length	Axle Combi		Steering Combi				
Gears	DFR	29/07/2020	YOM	2020	Runner? Yes/No	Yes	



Valid MOT Expires: 05/06/2025



No V5

Extras				Tyres & Wheels			Interior Condition		Service History	
Stereo: Interior: Sat Nav: Air Conditioning: Cruise Control	Radio Cloth No No Yes	Electric Windows: Central Locking: Phone Kit: Metallic Paint:	2 Yes BlueTooth No	Alloy Steel √	OSF Depth NSF Depth OSR Depth NSR Depth	mm mm mm	Carpets Upholstery Seats Odour Comments	Poor Good Poor Good	Service History Stamps	No











































Damage Lines

Component Bonnet

Bumper Front Wing nsf Qtr Panel nsr Qtr Panel nsr Qtr Panel nsr Qtr Panel nsr Bumper Rear Moulding Door nsr Door nsr Badgedecal Rear Door osr Qtr Panel osr Door osf Wing osf Door Mirror Assy osf **Carpets Front** Seat Base Cover osf Seat Base Cover nsf

Condition


Dented Scratched Dented Dented Dented Dented Dented Scuffed (Unpainted) Dented Dented Missing Dented Scratched Dented Dented Dented Dented Scratched Dented Scratched Broken Holed Holed Soiled

Severity

Over 30mm Over 100mm Thru Paint Over 30% Of Panel Over 30mm Over 30mm Over 30mm Over 30mm Over 100mm Over 30mm Over 30mm Replace Over 30mm Over 25mm Thru Paint Over 30mm Over 30mm Over 30mm Over 30mm Over 25mm Not Thru Paint Over 30mm Over 25mm Not Thru Paint Replace Over 3mm Over 3mm Heavy

Repair

Repair and Refinish Refinish Replace Repair and Refinish Repair and Refinish Repair and Refinish Repair and Refinish Smart Repair Repair and Refinish Repair and Refinish Replace Repair and Refinish Refinish Repair and Refinish Repair and Refinish Repair and Refinish Repair and Refinish Machine Polish Repair and Refinish Machine Polish Replace Replace Replace Replace



Splat Key

S3 Scratch/Paint defect 100m + D3 Dent/damage 100mm + K Crack/Torn M

Missing

Damage Assessment



Bonnet Dented Over

30mm Repair and Refinish



Bumper Front

Scratched

Over 100mm Thru Paint

Refinish



Wing nsf Dented Over 30% Of Panel

Replace



Qtr Panel nsr

Dented Over

30mm Repair and Refinish



Qtr Panel nsr Dented Over 30mm Repair and

Refinish

Door nsr

Dented

Over

30mm

Repair and

Refinish

Qtr Panel

Scratched

Thru Paint

Qtr Panel

osr

Dented

Over

30mm

Repair

Refinish

Door osf

Dented

Over

30mm

Repair

Carpets Front

and Refinish

and

Refinish

osr

Over

25mm

























Qtr Panel nsr

Dented

Over 30mm

Repair and Refinish

Bumper Rear Moulding

Scuffed (Unpainted)

Over 100mm

Smart Repair

Badgedecal Rear Missing Needs Replaced Replace

Qtr Panel osr Dented

osr Dented Over 30mm Repair and Refinish

Base Cover



Qtr Panel nsr

Dented

Over 30mm

Repair and Refinish

Door nsr

Dented

Over

30mm

Repair

Refinish

and





a a a a BM

Door osr

Dented Over 30mm Repair and Refinish



Qtr Panel osr Dented Over

30mm Repair and Refinish

Qtr Panel osr

Scratched

Over 25mm Not Thru Paint

-

Machine Polish

Door Mirror Assy osf

Broken

Needs Replaced

Replace

Seat Base Cover

Wing osf Scratched Over

Thru Paint











Seat

25mm Not

Machine Polish





osf Holed Over 3mm Replace



nsf Soiled Heavy Replace

Comments

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.

The details within this inspection report are correct at point of vehicle arrival. Updates, errors and omissions will be highlighted by the CVA Auctions via catalogues, the website, entry forms or by the auctioneer.