



Carr Hill Industrial Estate
Doncaster
South Yorkshire
DN4 8DE
Tel: 01302 732600
Email: enquiries@cva-auctions.co.uk

Commercial Vehicle Auctions Ltd.

CE70KTO

CN: VF7VBYHRKL7061896

Photos



General Details

CITROEN DISPATCH 1000 1.5 BLUEHDI 100PS
ENTERPRISE

Vat Status: Commercial (plus Vat)

Mileage	69,651 miles	Miles Warranty	
Colour	Grey	Fuel	Diesel
Transmission	Manual	Fuel Level	
Reg Date	25/01/2021	Engine Size	
Body Type			

Details

Engine No	Cab Type	Plated Weight	Doors
Body Length	Axle Combi	Steering Combi	Rear Susp
Gears	6 DFR	YOM	Runner? Yes/No
	25/01/2021	2021	Yes



MOT Cert Here
Expires: 29/04/2025



V5 with CVA

Extras

Stereo:	HDD	Electric	2
Interior:	Vinyl	Windows:	
Sat Nav:	No	Central	Yes
Air	Yes	Locking:	
Conditioning:		Phone Kit:	BlueTooth
Cruise Control	Yes	Metallic	Yes
		Paint:	

Tyres & Wheels



Alloy	OSF Depth	mm
Steel ✓	NSF Depth	mm
	OSR Depth	mm
	NSR Depth	mm

Interior Condition

Carpets	Good
Upholstery	Good
Seats	Poor
Odour	Good
Comments	

Service History

Service	No
History	
Stamps	






Damage Lines

Component	Condition	Severity	Repair
Bonnet	Chipped	Multiple Chips	Refinish
Wing nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Qtr Panel nsr	Scratched	Over 25mm Thru Paint	Refinish
Qtr Panel nsr	Scratched	Over 25mm Thru Paint	Refinish
Qtr Panel nsr	Dented	Over 30mm	Repair and Refinish
Bumper Rear	Scratched	Over 100mm Thru Paint	Refinish
Qtr Panel osr	Scratched	Over 25mm Thru Paint	Refinish
Qtr Panel osr	Chipped	Multiple Chips	Refinish
Seat Base Cover osf	Soiled	Heavy	Replace
Screen Front	Chipped	Over 10mm	Replace

Vehicle Splat



Splat Key

S3
Scratch/Paint defect 100m +
D3
Dent/damage 100mm +
C2
Multiple Chips

Damage Assessment




Bonnet
Chipped
Multiple Chips
Refinish



Wing nsf
Scratched
Over 25mm Not Thru Paint



Qtr Panel nsr
Scratched
Over 25mm



Machine
Polish



Thru Paint
Refinish



**Qtr Panel
nsr**

Scratched

Over
25mm
Thru Paint

Refinish



**Qtr Panel
nsr**

Dented

Over
30mm

Repair
and
Refinish



**Bumper
Rear**

Scratched

Over
100mm
Thru Paint

Refinish



**Qtr Panel
osr**

Scratched

Over
25mm
Thru Paint

Refinish



**Qtr Panel
osr**

Chipped

Multiple
Chips

Refinish



**Seat
Base
Cover
osf**

Soiled

Heavy

Replace



**Screen
Front**

Chipped

Over
10mm

Replace

Comments

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.

The details within this inspection report are correct at point of vehicle arrival. Updates, errors and omissions will be highlighted by the CVA Auctions via catalogues, the website, entry forms or by the auctioneer.