



# Commercial Vehicle Auctions Ltd.

PN71BKV

CN: ZFA25000002R82769

## Photos



## General Details

FIAT DUCATO 35 MAXI 2.3 MULTIJET

Vat Status: Commercial (plus Vat)

|              |                |                |        |
|--------------|----------------|----------------|--------|
| Mileage      | 98,769 miles   | Miles Warranty |        |
| Colour       | Multi-coloured | Fuel           | Diesel |
| Transmission | Manual         | Fuel Level     |        |
| Reg Date     | 01/09/2021     | Engine Size    |        |
| Body Type    |                |                |        |

## Details

|             |            |                |                |
|-------------|------------|----------------|----------------|
| Engine No   | Cab Type   | Plated Weight  | Doors          |
| Body Length | Axle Combi | Steering Combi | Rear Susp      |
| Gears       | 6 DFR      | YOM            | Runner? Yes/No |
|             |            |                | Yes            |



Valid MOT  
Expires: 31/08/2025



No V5

## Extras

|                |       |            |           |
|----------------|-------|------------|-----------|
| Stereo:        | Radio | Electric   | 2         |
| Interior:      | Cloth | Windows:   |           |
| Sat Nav:       | No    | Central    | Yes       |
| Air            | No    | Locking:   |           |
| Conditioning:  |       | Phone Kit: | BlueTooth |
| Cruise Control | No    | Metallic   | No        |
|                |       | Paint:     |           |

## Tyres & Wheels





|         |           |    |
|---------|-----------|----|
| Alloy   | OSF Depth | mm |
| Steel ✓ | NSF Depth | mm |
|         | OSR Depth | mm |
|         | NSR Depth | mm |

## Interior Condition


|            |      |
|------------|------|
| Carpets    | Poor |
| Upholstery | Good |
| Seats      | Poor |
| Odour      | Poor |
| Comments   |      |

## Service History

|                 |    |
|-----------------|----|
| Service History | No |
| Stamps          |    |







| Damage Lines        |           |                      |          |
|---------------------|-----------|----------------------|----------|
| Component           | Condition | Severity             | Repair   |
| Bonnet              | Chipped   | Multiple Chips       | Refinish |
| Wing osf            | Scratched | Over 25mm Thru Paint | Refinish |
| Carpets Front       | Holed     | Over 3mm             | Replace  |
| Seat Base Cover osf | Holed     | Over 3mm             | Replace  |

Vehicle Splat

Splat Key

S3

Scratch/Paint defect 100m +

C2

Multiple Chips

Damage Assessment

Bonnet

Chipped

Multiple Chips

Refinish

Wing osf

Scratched

Over 25mm Thru Paint

Refinish

Carpets Front

Holed

Over 3mm

Replace

Seat Base Cover osf

Holed

Over 3mm

Replace

| Comments                                                                                                                                                                                   |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <p>reported "engine/oil issues"</p> <p><b>No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.</b></p> |

The details within this inspection report are correct at point of vehicle arrival. Updates, errors and omissions will be highlighted by the CVA Auctions via catalogues, the website, entry forms or by the auctioneer.