



Commercial Vehicle Auctions Ltd.

CK16UDH

CN: TYAFGB71ERDY09443

Photos



General Details

FUSO CANTER 6C18

Vat Status: Commercial (plus Vat)

Mileage	48,963 km	Miles Warranty	
Colour	White	Fuel	Diesel
Transmission	Manual	Fuel Level	
Reg Date	31/05/2016	Engine Size	
Body Type			

Details

Engine No	Cab Type	Crew Cab	Plated Weight	Doors	
Body Length	Axle Combi	4x2	Steering Combi	Rear Susp	Spring
Gears	5 DFR	31/05/2016	YOM	Runner? Yes/No	No



V5 with CVA

Extras



Stereo:	CD	Electric Windows:	2
Interior:	Cloth	Central Locking:	No
Sat Nav:	No	Phone Kit:	No
Air Conditioning:	No	Metallic Paint:	No
Cruise Control	No		

Interior Condition

Carpets	Good
Upholstery	Good
Seats	Good
Odour	
Comments	

Service History

Service History	No
Stamps	





Damage Lines			
Component	Condition	Severity	Repair
Unclassified	Major Parts Missing	Report Only	Report Only (Grade)
Bumper Front	Dented	Over 30mm	Repair and Refinish
Door nsf	Dented	Over 30mm	Repair and Refinish
Unclassified	Major Parts Missing	Report Only	Report Only (Grade)

Vehicle Splat

Splat Key

D3

Dent/damage 100mm +

M

Missing

Damage Assessment

Unclassified

Major Parts Missing

Report Only

Report Only (Grade)

Bumper Front

Dented

Over 30mm

Repair and Refinish

Door nsf

Dented

Over 30mm

Repair and Refinish

Unclassified

Major Parts Missing

Report Only

Report Only (Grade)

Comments

engine stripped

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.

The details within this inspection report are correct at point of vehicle arrival. Updates, errors and omissions will be highlighted by the CVA Auctions via catalogues, the website, entry forms or by the auctioneer.