



Commercial Vehicle Auctions Ltd.

YH12USX

CN: WF0XXXTTFXCA05439

Photos



General Details

FORD TRANSIT 330 2.2 TDCI 125PS

Vat Status: Commercial (plus Vat)

Mileage	68,502 miles	Miles Warranty	
Colour	White	Fuel	Diesel
Transmission	Manual	Fuel Level	
Reg Date	10/07/2012	Engine Size	
Body Type			

Details

Engine No	Cab Type	Plated Weight	Doors
Body Length	Axle Combi	Steering Combi	Rear Susp
Gears	6 DFR	10/07/2012 YOM	2012 Runner? Yes/No Yes



No V5

Extras

Stereo:	CD	Electric	2
Interior:	Cloth	Windows:	
Sat Nav:	No	Central	Yes
Air	No	Locking:	
Conditioning:		Phone Kit:	BlueTooth
Cruise Control	No	Metallic	No
		Paint:	

Tyres & Wheels



Alloy	OSF Depth	mm
Steel ✓	NSF Depth	mm
	OSR Depth	mm
	NSR Depth	mm

Interior Condition

Carpets	Good
Upholstery	Good
Seats	Good
Odour	Good
Comments	

Service History

Service History	No
Stamps	






Damage Lines

Component	Condition	Severity	Repair
Bonnet	Chipped	Multiple Chips	Refinish
Roof	Chipped	Multiple Chips	Refinish
Wing nsf	Rusted	Over 5mm	Refinish
Qtr Panel nsr	Dented	Over 30mm	Repair and Refinish
Qtr Panel nsr	Dented	Over 30mm	Repair and Refinish
Qtr Panel nsr	Chipped	Multiple Chips	Refinish
Qtr Panel nsr	Scratched	Over 25mm Thru Paint	Refinish
Sill os	Rusted	Over 5mm	Refinish
Wing osf	Rusted	Over 5mm	Refinish
Wing osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Wing osf	Rusted	Over 5mm	Refinish
Door osf	Chipped	Multiple Chips	Refinish

Vehicle Splat



Splat Key

S3
Scratch/Paint defect 100m +

D3
Dent/damage 100mm +

C2
Multiple Chips

R
Rust

Damage Assessment



Bonnet

Chipped
Multiple Chips
Refinish



Roof

Chipped
Multiple Chips
Refinish



Wing nsf

Rusted
Over 5mm
Refinish




Qtr Panel nsr

Dented



Qtr Panel nsr

Dented



Qtr Panel nsr

Chipped

	Over 30mm Repair and Refinish		Over 30mm Repair and Refinish		Multiple Chips Refinish
	Qtr Panel nsr Scratched Over 25mm Thru Paint Refinish		Sill os Rusted Over 5mm Refinish		Wing osf Rusted Over 5mm Refinish
	Wing osf Scratched Over 25mm Not Thru Paint Machine Polish		Wing osf Rusted Over 5mm Refinish		Door osf Chipped Multiple Chips Refinish

Comments	
No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.	

The details within this inspection report are correct at point of vehicle arrival. Updates, errors and omissions will be highlighted by the CVA Auctions via catalogues, the website, entry forms or by the auctioneer.