



# Commercial Vehicle Auctions Ltd.

MX69AUT

CN: VF1VA000162287752

## Photos



## General Details

RENAULT MASTER 2.3 DCI BUSINESS

Vat Status: Commercial (plus Vat)

|              |               |                |        |
|--------------|---------------|----------------|--------|
| Mileage      | 145,976 miles | Miles Warranty |        |
| Colour       | White         | Fuel           | Diesel |
| Transmission | Manual        | Fuel Level     |        |
| Reg Date     | 16/09/2019    | Engine Size    |        |
| Body Type    |               |                |        |

## Details

|             |            |                |                |
|-------------|------------|----------------|----------------|
| Engine No   | Cab Type   | Plated Weight  | Doors          |
| Body Length | Axle Combi | Steering Combi | Rear Susp      |
| Gears       | 6 DFR      | YOM            | Runner? Yes/No |
|             |            |                | Yes            |



Valid MOT  
Expires: 12/08/2025



No V5

## Extras

|                |       |            |           |
|----------------|-------|------------|-----------|
| Stereo:        | HDD   | Electric   | 2         |
| Interior:      | Cloth | Windows:   |           |
| Sat Nav:       | Yes   | Central    | Yes       |
| Air            | Yes   | Locking:   |           |
| Conditioning:  |       | Phone Kit: | BlueTooth |
| Cruise Control | Yes   | Metallic   | No        |
|                |       | Paint:     |           |

## Tyres & Wheels


|         |           |    |
|---------|-----------|----|
| Alloy   | OSF Depth | mm |
| Steel ✓ | NSF Depth | mm |
|         | OSR Depth | mm |
|         | NSR Depth | mm |

## Interior Condition

|            |      |
|------------|------|
| Carpets    | Good |
| Upholstery | Good |
| Seats      | Poor |
| Odour      | Good |
| Comments   |      |

## Service History

|         |    |
|---------|----|
| Service | No |
| History |    |
| Stamps  |    |



| Damage Lines          |                     |                      |              |
|-----------------------|---------------------|----------------------|--------------|
| Component             | Condition           | Severity             | Repair       |
| Bonnet                | Chipped             | Multiple Chips       | Refinish     |
| Qtr Panel nsr         | Scratched           | Over 25mm Thru Paint | Refinish     |
| Qtr Panel osr         | Scratched           | Over 25mm Thru Paint | Refinish     |
| Qtr Panel Moulding os | Scratched (Painted) | Over 25mm Thru Paint | Smart Repair |
| Seat Base Cover osf   | Holed               | Over 3mm             | Replace      |
| Screen Front          | Chipped             | Over 10mm            | Replace      |

Vehicle Splat

Splat Key

S3

Scratch/Paint defect 100m +

C1

Single Chip

C2

Multiple Chips

| Damage Assessment |                                                                                                         |  |                                                                                   |  |                                                                                   |
|-------------------|---------------------------------------------------------------------------------------------------------|--|-----------------------------------------------------------------------------------|--|-----------------------------------------------------------------------------------|
|                   | <b>Bonnet</b><br><br>Chipped<br><br>Multiple Chips<br><br>Refinish                                      |  | <b>Qtr Panel nsr</b><br><br>Scratched<br><br>Over 25mm Thru Paint<br><br>Refinish |  | <b>Qtr Panel osr</b><br><br>Scratched<br><br>Over 25mm Thru Paint<br><br>Refinish |
|                   | <b>Qtr Panel Moulding os</b><br><br>Scratched (Painted)<br><br>Over 25mm Thru Paint<br><br>Smart Repair |  | <b>Seat Base Cover osf</b><br><br>Holed<br><br>Over 3mm<br><br>Replace            |  | <b>Screen Front</b><br><br>Chipped<br><br>Over 10mm<br><br>Replace                |

#### Comments

**No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.**

The details within this inspection report are correct at point of vehicle arrival. Updates, errors and omissions will be highlighted by the CVA Auctions via catalogues, the website, entry forms or by the auctioneer.