



Commercial Vehicle Auctions Ltd.

YX22XCA

CN: LSH14J7C3MA160503

Photos



General Details

MAXUS DELIVER 9 2.0 DT 163PS

Vat Status: Commercial (plus Vat)

Mileage	56,607 km	Miles Warranty	No
Colour	White	Fuel	Diesel
Transmission	Manual	Fuel Level	Red
Reg Date	24/03/2022	Engine Size	
Body Type			

Details

Engine No	Cab Type	Plated Weight	Doors
Body Length	Axle Combi	Steering Combi	Rear Susp
Gears	6 DFR	24/03/2022 YOM	2022 Runner? Yes/No
			Yes



No V5

Extras

Stereo:	Radio	Electric	2
Interior:	Cloth	Windows:	
Sat Nav:	No	Central	Yes
Air	Yes	Locking:	
Conditioning:		Phone Kit:	BlueTooth
Cruise Control	No	Metallic	No
		Paint:	

Tyres & Wheels

Alloy	OSF	3mm-5mm
Steel ✓	Depth	mm
	NSF	3mm-5mm
	Depth	mm
	OSR	3mm-5mm
	Depth	mm
	NSR	3mm-5mm
	Depth	mm

Interior Condition

Carpets	Average
Upholstery	Average
Seats	Average
Odour	Average
Comments	

Service History

Service History	No
Stamps	



Damage Lines

Component

Sill os
Bumper Front
Wing osf
Door osf
Bumper Rear Moulding

Condition

Scratched
Chipped
Dented
Dented
Broken

Severity

Over 25mm Thru Paint
Multiple Chips
With Paint Damage
With Paint Damage
Replace

Repair

Refinish
Smart Repair
Repair and Refinish
Repair and Refinish
Replace

Badgedecal Rear	Missing	Replace	Replace
Qtr Panel nsr	Dented	Between 10mm + 30mm	Smart Repair
Door nsr	Dented	Over 30mm	Repair and Refinish
Flasher Side Repeater ns	Broken	Replace	Replace

Vehicle Splat

Splat Key

S2
Scratch/Paint defect 30-100mm

D2
Dent/damage 30-100mm

D3
Dent/damage 100mm +

C2
Multiple Chips

X
Req Replacement

M
Missing

Damage Assessment

Sill os

Scratched

Over 25mm Thru Paint

Refinish

Bumper Front

Chipped

Multiple Chips

Smart Repair

Wing osf

Dented

With Paint Damage

Repair and Refinish

Door osf

Dented

With Paint Damage

Repair and Refinish

Bumper Rear Moulding

Broken

Needs Replaced

Replace

Badgedecal Rear

Missing

Needs Replaced

Replace

Qtr Panel nsr

Dented

Between 10mm + 30mm

Smart Repair

Door nsr

Dented

Over 30mm

Repair and Refinish

Flasher Side Repeater ns

Broken

Needs Replaced

Replace

Comments

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.

The details within this inspection report are correct at point of vehicle arrival. Updates, errors and omissions will be highlighted by the CVA Auctions via catalogues, the website, entry forms or by the auctioneer.