



Commercial Vehicle Auctions Ltd.

FJ14DBU

CN: ZFA25000002517063

Photos



General Details

FIAT DUCATO 35 2.3 MAXI MULTIJET

Vat Status: Commercial (plus Vat)

Mileage	64,948 miles	Miles Warranty	
Colour	Red	Fuel	Diesel
Transmission	Auto	Fuel Level	
Reg Date	20/03/2014	Engine Size	
Body Type			

Details

Engine No	Cab Type	Plated Weight	Doors
Body Length	Axle Combi	Steering Combi	Rear Susp
Gears	DFR	YOM	Runner? Yes/No
	20/03/2014	2014	Yes



Valid MOT
Expires: 22/12/2025



No V5

Extras

Stereo:	CD	Electric	2
Interior:	Cloth	Windows:	
Sat Nav:	No	Central Locking:	Yes
Air	No	Phone Kit:	No
Conditioning:		Metallic Paint:	No
Cruise Control	No		

Tyres & Wheels




Alloy	OSF Depth	mm
Steel ✓	NSF Depth	mm
	OSR Depth	mm
	NSR Depth	mm

Interior Condition

Carpets	Poor
Upholstery	Poor
Seats	Poor
Odour	Poor
Comments	

Service History

Service History	No
Stamps	






Damage Lines

Component	Condition	Severity	Repair
Bonnet	Dented	Over 30mm	Repair and Refinish
Bumper Front	Cracked	Over 25mm	Replace
Door nsf	Chipped	Multiple Chips	Refinish
Door Moulding nsf	Missing	Replace	Replace
Wing Front Arch Extension os	Scuffed (Unpainted)	Over 100mm	Smart Repair
Door osf	Scratched	Over 25mm Thru Paint	Refinish
Door Pad osf	Soiled	Heavy	Replace
Carpets Front	Torn	Over 10mm	Replace
Seat Base Cover osf	Soiled	Heavy	Replace
Seat Base Cover nsf	Soiled	Heavy	Replace
Door Pad nsf	Soiled	Heavy	Replace

Vehicle Splat

Splat Key

S3
Scratch/Paint defect 100m +
D3
Dent/damage 100mm +
C2
Multiple Chips
K
Crack/Torn



M
Missing

Damage Assessment



Bonnet

Dented
Over
30mm
Repair
and
Refinish




Bumper Front

Cracked
Over
25mm
Replace



Door nsf

Chipped
Multiple
Chips
Refinish



Door Moulding nsf

Missing
Needs
Replaced
Replace



Wing Front Arch Extension os

Scuffed
(Unpainted)
Over
100mm
Smart
Repair



Door osf

Scratched
Over
25mm
Thru Paint
Refinish



Door Pad osf

Soiled
Heavy
Replace




Carpets Front

Torn
Over
10mm
Replace



Seat Base Cover osf

Soiled
Heavy
Replace



Seat Base Cover nsf

Soiled
Heavy
Replace



Door Pad nsf

Soiled
Heavy
Replace

Comments

wipers inop

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.

The details within this inspection report are correct at point of vehicle arrival. Updates, errors and omissions will be highlighted by the CVA Auctions via catalogues, the website, entry forms or by the auctioneer.