



## Commercial Vehicle Auctions Ltd.

SK63MFN

CN: TMBFK25J2E3013579

### Photos



### General Details

SKODA FABIA GREENLINE 1.2 TDI

Vat Status:

<b>Mileage</b>	138,668 miles	<b>Miles Warranty</b>	
<b>Colour</b>	White	<b>Fuel</b>	Diesel
<b>Transmission</b>	Manual	<b>Fuel Level</b>	
<b>Reg Date</b>	14/10/2013	<b>Engine Size</b>	
<b>Body Type</b>			



**Valid MOT**  
**Expires: 18/11/2025**



**V5 with CVA**

### Extras

<b>Stereo:</b>	CD	<b>Electric</b>	2
<b>Interior:</b>	Cloth	<b>Windows:</b>	
<b>Sat Nav:</b>	No	<b>Central Locking:</b>	Yes
<b>Air</b>	No	<b>Phone Kit:</b>	No
<b>Conditioning:</b>		<b>Metallic Paint:</b>	No
<b>Cruise Control</b>	No		

### Tyres & Wheels

<b>Alloy</b> ✓	<b>OSF</b>	3mm-5mm
<b>Steel</b>	<b>Depth</b>	mm
	<b>NSF</b>	3mm-5mm
	<b>Depth</b>	mm
	<b>OSR</b>	3mm-5mm
	<b>Depth</b>	mm
	<b>NSR</b>	3mm-5mm
	<b>Depth</b>	mm


### Interior Condition

<b>Carpets</b>	Average
<b>Upholstery</b>	Average
<b>Seats</b>	Average
<b>Odour</b>	Average
<b>Comments</b>	

### Service History

<b>Service History</b>	No
<b>Stamps</b>	

## Photos



## Damage Lines

Component	Condition	Severity	Repair
Bonnet	Chipped	1 To 5	Smart Repair
Wheel osf	Corroded	Light	Smart Repair
Sill os	Rusted	Over 5mm	Refinish
Door osf	Dented	Between 10mm + 30mm	Smart Repair
Bumper Rear	Cracked	Over 25mm	Replace



Sill ns	Rusted	Over 5mm	Refinish
Wheel nsf	Dented	Over 30mm (Alloy)	Replace

Vehicle Splat

Splat Key

**D1**  
Dent/damage under 30mm

**C2**  
Multiple Chips

**R**  
Rust

Damage Assessment

**Bonnet**  
Chipped  
1 To 5  
Smart Repair

**Wheel osf**  
Corroded  
Light  
Smart Repair

**Sill os**  
Rusted  
Over 5mm  
Refinish

**Door osf**  
Dented  
Between 10mm + 30mm  
Smart Repair

**Bumper Rear**  
Cracked  
Over 25mm  
Replace

**Sill ns**  
Rusted  
Over 5mm  
Refinish

**Wheel nsf**  
Dented  
Over 30mm (Alloy)  
Replace

Comments

NON RUNNER DOESNT START OR DRIVE

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.

The details within this inspection report are correct at point of vehicle arrival. Updates, errors and omissions will be highlighted by the CVA Auctions via catalogues, the website, entry forms or by the auctioneer.