



Commercial Vehicle Auctions Ltd.

SN18WDF

CN: WF0XXXTTGXHP42701

Photos



General Details

FORD TRANSIT 350 2.0 TDCI 130PS

Vat Status: Commercial (plus Vat)

Mileage	133,711 miles	Miles Warranty	
Colour	White	Fuel	Diesel
Transmission	Manual	Fuel Level	
Reg Date	08/03/2018	Engine Size	
Body Type			

Details

Engine No	Cab Type	Plated Weight	Doors
Body Length	Axle Combi	Steering Combi	Rear Susp
Gears	6 DFR	YOM	Runner? Yes/No
		2018	Yes

No V5

Extras

Stereo:	Radio	Electric	2
Interior:	Cloth	Windows:	
Sat Nav:	No	Central	Yes
Air	No	Locking:	
Conditioning:		Phone Kit:	BlueTooth
Cruise Control	No	Metallic	No
		Paint:	

Tyres & Wheels




Alloy	OSF Depth	mm
Steel ✓	NSF Depth	mm
	OSR Depth	mm
	NSR Depth	mm

Interior Condition

Carpets	Good
Upholstery	Average
Seats	Poor
Odour	Poor
Comments	

Service History

Service	No
History	
Stamps	






Damage Lines

Component	Condition	Severity	Repair
Bonnet	Chipped	Multiple Chips	Refinish
Wing nsf	Chipped	Multiple Chips	Refinish
Door Mirror Glass ns	Broken	Replace	Replace
Door Moulding nsf	Missing	Replace	Replace
Qtr Panel nsr	Dented	Over 30mm	Repair and Refinish
Qtr Panel nsr	Dented	Over 30mm	Repair and Refinish
Qtr Panel nsr	Dented	Over 30mm	Repair and Refinish
Qtr Panel nsr	Dented	Over 30mm	Repair and Refinish
Qtr Panel nsr	Dented	Over 30mm	Repair and Refinish
Qtr Panel nsr	Dented	Over 30mm	Repair and Refinish
C Post ns	Dented	Over 30mm	Repair and Refinish
Bumper Rear Moulding	Missing	Replace	Replace
Door nsr	Dented	Over 30mm	Repair and Refinish
Door nsr	Dented	Over 30mm	Repair and Refinish
Door osr	Dented	Over 30mm	Repair and Refinish
Qtr Panel nsr	Dented	Over 30mm	Repair and Refinish
Qtr Panel osr	Dented	Over 30mm	Repair and Refinish
Qtr Panel Moulding os	Scuffed (Unpainted)	Over 100mm	Smart Repair
Qtr Panel osr	Dented	Over 30mm	Repair and Refinish
Qtr Panel osr	Dented	Over 30mm	Repair and Refinish
Seat Base Cover osf	Soiled	Heavy	Replace
Seat Base Cover nsf	Soiled	Heavy	Replace

Vehicle Splat



Splat Key

S3

Scratch/Paint defect 100m +

D3

Dent/damage 100mm +

C2

Multiple Chips


K

Crack/Torn

M

Missing

Damage Assessment




Bonnet

Chipped

Multiple Chips

Refinish




Wing nsf

Chipped

Multiple Chips

Refinish




Door Mirror Glass ns

Broken

Needs Replaced

Replace




Door Moulding nsf

Missing

Needs Replaced

Replace




Qtr Panel nsr

Dented

Over 30mm

Repair and Refinish




Qtr Panel nsr

Dented

Over 30mm

Repair and Refinish




Qtr Panel nsr

Dented

Over 30mm

Repair and Refinish




Qtr Panel nsr

Dented

Over 30mm

Repair and Refinish




Qtr Panel nsr

Dented

Over 30mm

Repair and Refinish




Qtr Panel nsr

Dented

Over 30mm

Repair and




C Post ns

Dented

Over 30mm

Repair and Refinish



Bumper Rear Moulding

Missing

Needs Replaced

Replace

Refinish




Door nsr

Dented

Over
30mm

Repair
and
Refinish



Door nsr

Dented

Over
30mm

Repair
and
Refinish



Door osr

Dented

Over
30mm

Repair
and
Refinish



**Qtr Panel
nsr**

Dented

Over
30mm

Repair
and
Refinish



**Qtr Panel
osr**

Dented

Over
30mm

Repair
and
Refinish



**Qtr Panel
Moulding
os**

Scuffed
(Unpainted)

Over
100mm

Smart
Repair



**Qtr Panel
osr**

Dented

Over
30mm

Repair
and
Refinish



**Qtr Panel
osr**

Dented

Over
30mm

Repair
and
Refinish



**Seat
Base
Cover
osf**

Soiled

Heavy

Replace



**Seat
Base
Cover
nsf**

Soiled

Heavy

Replace



**Screen
Front**

Chipped

Over
10mm

Replace

Comments

welfare unit, alternator/battery failure.

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.

The details within this inspection report are correct at point of vehicle arrival. Updates, errors and omissions will be highlighted by the CVA Auctions via catalogues, the website, entry forms or by the auctioneer.