



Commercial Vehicle Auctions Ltd.

FN69AVC

CN: XLRAEL1500L490407

Photos



General Details

DAF LF 180 EURO 6 7.5 TONNE

Vat Status: Commercial (plus Vat)

Mileage	154,487 km	Miles Warranty	
Colour	White	Fuel	Diesel
Transmission	Manual	Fuel Level	
Reg Date	04/10/2019	Engine Size	
Body Type			

Details

Engine No	Cab Type	Day Cab	Plated Weight	Doors	
Body Length	Axle Combi	4x2	Steering Combi	Rear Susp	Spring
Gears	6 DFR	04/10/2019	YOM	2019	Runner? Yes/No
					Yes



Valid MOT
Expires: 28/02/2025



No V5

Extras




Stereo:	CD	Electric Windows:	2
Interior:	Cloth	Central Locking:	Yes
Sat Nav:	No	Phone Kit:	No
Air Conditioning:	No	Metallic Paint:	No
Cruise Control	Yes		

Interior Condition

Carpets	Good
Upholstery	Good
Seats	Poor
Odour	
Comments	

Service History

Service History	No
Stamps	



Damage Lines

Component	Condition	Severity	Repair
Bumper Front	Scratched	Over 100mm Thru Paint	Refinish
Panel Front	Scratched	Over 25mm Thru Paint	Refinish
Wing nsf	Scratched	Over 25mm Thru Paint	Refinish
Qtr Panel nsr	Scratched	Over 25mm Thru Paint	Refinish
Qtr Panel nsr	Scratched	Over 25mm Thru Paint	Refinish

Qtr Panel osr	Scratched	Over 25mm Thru Paint	Refinish
Qtr Panel osr	Scratched	Over 25mm Thru Paint	Refinish
Door osf	Scratched	Over 25mm Thru Paint	Refinish
Seat Base Cover osf	Torn	Over 3mm	Replace
Seat Base Cover nsf	Soiled	Heavy	Replace
Dash Warning Lights	Displayed	No Action	Report Only

Vehicle Splat

Splat Key

S3
Scratch/Paint defect 100m +

Damage Assessment

Bumper Front

Scratched
Over 100mm Thru Paint
Refinish

Panel Front

Scratched
Over 25mm Thru Paint
Refinish

Wing nsf

Scratched
Over 25mm Thru Paint
Refinish

Qtr Panel nsr

Scratched
Over 25mm Thru Paint
Refinish

Qtr Panel nsr

Scratched
Over 25mm Thru Paint
Refinish

Qtr Panel osr

Scratched
Over 25mm Thru Paint
Refinish

Seat Base Cover nsf

Torn
Over 3mm
Replace

Dash Warning Lights

Displayed

Seat Base Cover osf

Torn
Over 3mm
Replace



Soiled



Heavy

No Action

Replace

Report
Only

Comments

eml, emissions, adblue warnings displayed

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.

The details within this inspection report are correct at point of vehicle arrival. Updates, errors and omissions will be highlighted by the CVA Auctions via catalogues, the website, entry forms or by the auctioneer.