



Commercial Vehicle Auctions Ltd.

FN69AXX

CN: XLRAEL1500L489978

Photos



General Details

DAF LF 180 EURO 6 7.5 TONNE

Vat Status: Commercial (plus Vat)

Mileage	208,781 km	Miles Warranty	
Colour	White	Fuel	Diesel
Transmission	Manual	Fuel Level	
Reg Date	04/10/2019	Engine Size	
Body Type			

Details

Engine No	Cab Type	Day Cab	Plated Weight	Doors	
Body Length	Axle Combi	4x2	Steering Combi	Rear Susp	Spring
Gears	6 DFR	04/10/2019	YOM	Runner? Yes/No	Yes



Valid MOT
Expires: 31/01/2026



No V5

Extras




Stereo:	CD	Electric Windows:	2
Interior:	Cloth	Central Locking:	Yes
Sat Nav:	No	Phone Kit:	No
Air Conditioning:	No	Metallic Paint:	No
Cruise Control	Yes		

Interior Condition

Carpets	Good
Upholstery	Poor
Seats	Poor
Odour	
Comments	

Service History

Service History	No
Stamps	





Damage Lines


Component	Condition	Severity	Repair
Door osf	Scratched	Over 25mm Thru Paint	Refinish
Wing osf	Scratched	Over 25mm Thru Paint	Refinish
Bonnet	Chipped	Multiple Chips	Refinish
Wing nsf	Scratched	Over 25mm Thru Paint	Refinish
Door nsf	Dented	Over 30mm	Repair and Refinish
Qtr Panel nsr	Scratched	Over 25mm Thru Paint	Refinish
Qtr Panel nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Qtr Panel nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Qtr Panel osr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Qtr Panel osr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Seat Base Cover osf	Torn	Over 3mm	Replace
Door Pad osf	Soiled	Heavy	Replace
Seat Base Cover nsf	Soiled	Heavy	Replace

Vehicle Splat

Splat Key

S3
Scratch/Paint defect 100m +
D2
Dent/damage 30-100mm
C2

Multiple Chips



Damage Assessment



Door osf

Scratched
Over
25mm
Thru Paint
Refinish



Wing osf

Scratched
Over
25mm
Thru Paint
Refinish



Bonnet

Chipped
Multiple
Chips
Refinish



Wing nsf

Scratched
Over
25mm
Thru Paint
Refinish



Door nsf

Dented
Over
30mm
Repair
and
Refinish




**Qtr Panel
nsr**

Scratched
Over
25mm
Thru Paint
Refinish



**Qtr Panel
nsr**

Scratched
Over
25mm Not
Thru Paint
Machine
Polish



**Qtr Panel
nsr**

Scratched
Over
25mm Not
Thru Paint
Machine
Polish




**Qtr Panel
osr**

Scratched
Over
25mm Not
Thru Paint
Machine
Polish



**Qtr Panel
osr**

Scratched
Over
25mm Not
Thru Paint
Machine
Polish



**Seat
Base
Cover
osf**

Torn
Over 3mm
Replace



**Door Pad
osf**

Soiled
Heavy
Replace



**Seat
Base
Cover
nsf**

Soiled
Heavy

Replace

Comments

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.

The details within this inspection report are correct at point of vehicle arrival. Updates, errors and omissions will be highlighted by the CVA Auctions via catalogues, the website, entry forms or by the auctioneer.