



Commercial Vehicle Auctions Ltd.

SG15EVL

CN: WDB9630032L956830

Photos



General Details

MERCEDES-BENZ ANTOS 1827 BLUETEC 6

Vat Status: Commercial (plus Vat)

Mileage	239,964 km	Miles Warranty	No
Colour	White	Fuel	Diesel
Transmission	Auto	Fuel Level	Full
Reg Date	18/08/2015	Engine Size	
Body Type			

Details

Engine No	Cab Type	Day Cab	Plated Weight	Doors	
Body Length	Axle Combi	4x2	Steering Combi	Rear Susp	Spring
Gears	DFR	18/08/2015	YOM	Runner? Yes/No	Yes



Valid MOT
Expires: 30/04/2025



No V5



Extras


Interior Condition

Carpets	Average
Upholstery	Average
Seats	Average
Odour	
Comments	

Service History

Service History	No
Stamps	





Damage Lines			
Component	Condition	Severity	Repair
Door osf	Chipped	Multiple Chips	Refinish
A Post os	Scratched	UpTo 25mm Not Thru Paint	Machine Polish
Bumper Front	Scratched	UpTo 25mm Not Thru Paint	Machine Polish
Wing osf	Scratched	UpTo 25mm Not Thru Paint	Machine Polish
A Post ns	Scratched	UpTo 25mm Not Thru Paint	Machine Polish
Qtr Panel nsr	Scratched	UpTo 25mm Not Thru Paint	Machine Polish
Qtr Panel nsr	Scratched	UpTo 25mm Not Thru Paint	Machine Polish
Qtr Panel nsr	Scratched	UpTo 25mm Not Thru Paint	Machine Polish
Door osr	Cracked	Replace	Replace
Qtr Panel osr	Cracked	Replace	Replace
Qtr Panel osr	Cracked	Replace	Replace

Damage Assessment					
	Door osf Chipped Multiple Chips Refinish		A Post os Scratched UpTo 25mm Not Thru Paint Machine Polish		Bumper Front Scratched UpTo 25mm Not Thru Paint Machine Polish
	Wing osf Scratched UpTo 25mm Not Thru Paint Machine Polish		A Post ns Scratched UpTo 25mm Not Thru Paint Machine Polish		Qtr Panel nsr Scratched UpTo 25mm Not Thru Paint Machine Polish
	Qtr Panel nsr Scratched UpTo 25mm Not Thru Paint Machine Polish		Qtr Panel nsr Scratched UpTo 25mm Not Thru Paint Machine Polish		Door osr Cracked Needs Replaced Replace
	Qtr Panel osr Cracked Needs Replaced Replace		Qtr Panel osr Cracked Needs Replaced Replace		

Comments

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.

The details within this inspection report are correct at point of vehicle arrival. Updates, errors and omissions will be highlighted by the CVA Auctions via catalogues, the website, entry forms or by the auctioneer.