



Commercial Vehicle Auctions Ltd.

PJ20KXL

CN: W1V9076352P253056

Photos



General Details

MERCEDES-BENZ SPRINTER 314 CDI

Vat Status: Commercial (plus Vat)

Mileage	183,557 miles	Miles Warranty	
Colour	White	Fuel	Diesel
Transmission	Manual	Fuel Level	
Reg Date	17/07/2020	Engine Size	
Body Type			

Details

Engine No	Cab Type	Plated Weight	Doors
Body Length	Axle Combi	Steering Combi	Rear Susp
Gears	DFR	YOM	Runner? Yes/No
	17/07/2020	2020	Yes



Valid MOT
Expires: 04/05/2025



V5 with CVA

Extras

Stereo:	Radio	Electric	2
Interior:	Cloth	Windows:	
Sat Nav:	No	Central	Yes
Air	No	Locking:	
Conditioning:		Phone Kit:	BlueTooth
Cruise Control	Yes	Metallic	No
		Paint:	

Tyres & Wheels




Alloy	OSF Depth	mm
Steel ✓	NSF Depth	mm
	OSR Depth	mm
	NSR Depth	mm

Interior Condition

Carpets	Good
Upholstery	Good
Seats	Poor
Odour	Good
Comments	

Service History

Service	No
History	
Stamps	



Damage Lines			
Component	Condition	Severity	Repair
Bonnet	Chipped	Multiple Chips	Refinish
Qtr Panel nsr	Dented	Over 30mm	Repair and Refinish
Qtr Panel nsr	Dented	Over 30mm	Repair and Refinish
Qtr Panel nsr	Dented	Over 30mm	Repair and Refinish
Qtr Panel nsr	Dented	Over 30mm	Repair and Refinish
Qtr Panel nsr	Dented	Over 30mm	Repair and Refinish
Qtr Panel nsr	Dented	Over 30mm	Repair and Refinish
Badgedecal Rear	Broken	Replace	Replace
Door osr	Dented	Over 30mm	Repair and Refinish
Qtr Panel osr	Dented	Over 30mm	Repair and Refinish
Qtr Panel osr	Dented	Over 30mm	Repair and Refinish
Qtr Panel osr	Dented	Over 30mm	Repair and Refinish
Seat Base Cover osf	Holed	Over 3mm	Replace
Seat Base Cover nsf	Soiled	Heavy	Replace

Vehicle Splat

Splat Key

D3
Dent/damage 100mm +

C2
Multiple Chips

M
Missing

Damage Assessment					
	Bonnet Chipped Multiple Chips Refinish		Qtr Panel nsr Dented Over 30mm Repair and Refinish		Qtr Panel nsr Dented Over 30mm Repair and Refinish
	Qtr Panel nsr Dented Over 30mm Repair and Refinish		Qtr Panel nsr Dented Over 30mm Repair and Refinish		Qtr Panel nsr Dented Over 30mm Repair and Refinish



**Qtr Panel
nsr**

Dented

Over
30mm

Repair
and
Refinish



**Badgedecal
Rear**

Broken

Needs
Replaced

Replace



Door osr

Dented

Over
30mm

Repair
and
Refinish



**Qtr Panel
osr**

Dented

Over
30mm

Repair
and
Refinish



**Qtr Panel
osr**

Dented

Over
30mm

Repair
and
Refinish



**Qtr Panel
osr**

Dented

Over
30mm

Repair
and
Refinish



**Seat
Base
Cover
osf**

Holed

Over 3mm

Replace



**Seat
Base
Cover
nsf**

Soiled

Heavy

Replace

Comments

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.

The details within this inspection report are correct at point of vehicle arrival. Updates, errors and omissions will be highlighted by the CVA Auctions via catalogues, the website, entry forms or by the auctioneer.