



Commercial Vehicle Auctions Ltd.

MF70BMU

CN: VF7YCBNFC12P63946



General Details

CITROEN RELAY 35 2.2 BLUE HDI 140PS
ENTERPRISE


Vat Status: Commercial (plus Vat)

Mileage	92,978 miles	Miles Warranty	
Colour	White	Fuel	Diesel
Transmission	Manual	Fuel Level	
Reg Date	30/10/2020	Engine Size	
Body Type			

Details							
Engine No	Cab Type		Plated Weight		Doors		
Body Length	Axle Combi		Steering Combi		Rear Susp		
Gears	6 DFR	30/10/2020	YOM	2020	Runner? Yes/No	Yes	

No V5

Extras				Tyres & Wheels			Interior Condition		Service History	
Stereo:	Radio	Electric	2	Alloy	OSF Depth	mm	Carpets	Poor	Service	No
Interior:	Cloth	Windows:		Steel ✓	NSF Depth	mm	Upholstery	Good	History	
Sat Nav:	Yes	Central	Yes		OSR Depth	mm	Seats	Poor	Stamps	
Air	Yes	Locking:			NSR Depth	mm	Odour	Good		
Conditioning:		Phone Kit:	BlueTooth				Comments			
Cruise Control	Yes	Metallic	No							
		Paint:								






Damage Lines

Component	Condition	Severity	Repair
Bonnet	Chipped	Multiple Chips	Refinish
Roof	Dented	Over 30mm	Repair and Refinish
Door Mirror Assy nsf	Broken	Replace	Replace
Unclassified	Substantial Accident Damage	Report Only	Report Only (Grade)
Door osr	Dented	Over 30mm	Repair and Refinish
Door nsr	Dented	Over 30mm	Repair and Refinish
Door osr	Chipped	Multiple Chips	Refinish
Unclassified	Substantial Accident Damage	Report Only	Report Only (Grade)
Carpets Front	Torn	Over 10mm	Replace
Seat Base Cover nsf	Soiled	Heavy	Replace
Door Mirror Assy osf	Broken	Replace	Replace

Vehicle Splat



Splat Key

D3
Dent/damage 100mm +
C2
Multiple Chips
K
Crack/Torn

Damage Assessment



Bonnet

Chipped
Multiple Chips
Refinish



Roof

Dented
Over 30mm
Repair and Refinish



Door Mirror Assy nsf

Broken
Needs Replaced
Replace



Unclassified

Substantial Accident Damage



Door osr

Dented
Over



Door nsr

Dented
Over

	Report Only		30mm		30mm
	Report Only (Grade)		Repair and Refinish		Repair and Refinish
	Door osr Chipped Multiple Chips Refinish		Unclassified Substantial Accident Damage Report Only Report Only (Grade)		Carpets Front Torn Over 10mm Replace
	Seat Base Cover nsf Soiled Heavy Replace		Door Mirror Assy osf Broken Needs Replaced Replace		

Comments					
No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.					

The details within this inspection report are correct at point of vehicle arrival. Updates, errors and omissions will be highlighted by the CVA Auctions via catalogues, the website, entry forms or by the auctioneer.