



Commercial Vehicle Auctions Ltd.

MX69ATN

CN: VF1VA000X62549347

Photos



General Details

RENAULT MASTER LL35 2.3 DCI BUSINESS

Vat Status: Commercial (plus Vat)

Mileage	130,886 miles	Miles Warranty	
Colour	White	Fuel	Diesel
Transmission	Manual	Fuel Level	
Reg Date	16/09/2019	Engine Size	
Body Type			

Details

Engine No	Cab Type	Plated Weight	Doors
Body Length	Axle Combi	Steering Combi	Rear Susp
Gears	6 DFR	YOM	Runner? Yes/No
		2019	Yes



Valid MOT
Expires: 15/09/2025



V5 with CVA

Extras

Stereo:	HDD	Electric	2
Interior:	Cloth	Windows:	
Sat Nav:	Yes	Central	Yes
Air	Yes	Locking:	
Conditioning:		Phone Kit:	BlueTooth
Cruise Control	Yes	Metallic	No
		Paint:	

Tyres & Wheels



Alloy	OSF Depth	mm
Steel ✓	NSF Depth	mm
	OSR Depth	mm
	NSR Depth	mm

Interior Condition


Carpets	Poor
Upholstery	Good
Seats	Poor
Odour	Good
Comments	



Service History

Service	No
History	
Stamps	



Damage Lines			
Component	Condition	Severity	Repair
Bonnet	Chipped	Multiple Chips	Refinish
Qtr Panel Trim ns	Broken	Replace	Replace
Door nsf	Scratched	Over 25mm Thru Paint	Refinish
Qtr Panel Trim ns	Broken	Replace	Replace
Qtr Panel nsr	Cracked	Replace	Replace
Qtr Panel Moulding ns	Scuffed (Unpainted)	Over 100mm	Smart Repair
Carpets Front	Torn	Over 10mm	Replace
Seat Base Cover osf	Holed	Over 3mm	Replace
Screen Front	Chipped	Over 10mm	Replace

Vehicle Splat	Splat Key
	S3 Scratch/Paint defect 100m + C1 Single Chip C2 Multiple Chips K Crack/Torn

Damage Assessment					
	Bonnet Chipped Multiple Chips Refinish		Qtr Panel Trim ns Broken Needs Replaced Replace		Door nsf Scratched Over 25mm Thru Paint Refinish
	Qtr Panel Trim ns Broken Needs Replaced Replace		Qtr Panel nsr Cracked Needs Replaced Replace		Qtr Panel Moulding ns Scuffed (Unpainted) Over 100mm Smart Repair
	Carpets Front Torn Over 10mm		Seat Base Cover osf Holed		Screen Front Chipped Over 10mm

Replace

Over 3mm

Replace

Replace

Comments

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.

The details within this inspection report are correct at point of vehicle arrival. Updates, errors and omissions will be highlighted by the CVA Auctions via catalogues, the website, entry forms or by the auctioneer.