

VEHICLE INSPECTION REPORT

013392

HAMM HA13

Inspection

Vehicle

VAT

V5

N/A

Details

Reg. date

Year 2016

Mileage 843 Hours Warranted

Fuel Type

Diesel

Colour

VIN

112013392

Body Style

ROLLER

Gearbox

Hydrostatic

Axle Combi

Tandem

COLLECTION FROM WIGAN

Tyres

NSF

NSR

OSF

OSR

Spare

Photos



