

VEHICLE INSPECTION REPORT

FN19KMV

Daf XF 480

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 Buyer To Apply

Details

Reg. date	29/04/2019	VIN	XLRTGH4300G255953	Axle Combi	6x2
Year	2019	Body Style	Tractor Unit	Steering Combi	Mid-Lift
Mileage	417,955 Miles Not Warranted	MOT Due	31/07/2026	Rear Suspension	Air
Fuel Type	Diesel	Cab Type	SUPER SPACE CAB		
Colour	WHITE	Gearbox	AUTOMATIC		

LOCATED NEAR SWINDON *WARNING LIGHT ON DASH*

Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Air conditioning

Photos





Condition Check



Damage Photos



1: Door osf
Scratched
UpTo 25mm Thru Paint

2: Bumper Front
Cracked
UpTo 25mm

Interior

Carpet Condition -
Seat Condition -

Upholstery Condition -
Odour -

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK