

VEHICLE INSPECTION REPORT

FN19KLO

Daf XF 480

Non Runner

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date	29/04/2019	Colour	WHITE	Gearbox	AUTOMATIC
Year	2019	VIN	XLRTGH4300G256713	Axle Combi	6x2
Mileage	Not Showing	Body Style	Tractor Unit	Steering Combi	Mid-Lift
Fuel Type	Diesel	Cab Type	SUPER SPACE CAB	Rear Suspension	Air

LOCATED NEAR SWINDON *NON RUNNER - ENGINE STRIPPED* MOT SHOWS 659,293KM 25/11/2024

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4


Features

- Air conditioning


Photos







Condition Check



Damage Photos



1: B Post ns
Scratched
UpTo 25mm Thru Paint

Interior

Carpet Condition	-	Upholstery Condition	-
Seat Condition	-	Odour	-

Engine Runs	Fault	Gearbox 1st and Reverse Test	Fault
Brakes	Fault	Clutch Slip Test from Static	Fault
Parking Brake	Fault	Gearbox Static Gear Selection (engine running)	Fault
		No Excessive Smoking	Fault
EML light illuminated	Fault	Oil warning light illuminated	Fault
Airbag light illuminated	Fault	DPF light illuminated	Fault
ABS light illuminated	Fault	Service indicator light illuminated	Fault