

VEHICLE INSPECTION REPORT

GM18NOU

Volvo FH 500

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 10/07/2018

Year 2018

Mileage 668,991 Km Not Warranted

Fuel Type Diesel

Colour WHITE

VIN YV2RT40C8JB873636

Body Style Tractor Unit

MOT Due 31/01/2026

Cab Type XL GLOBETROTTER CAB

Gearbox AUTOMATIC

Steering Combi Mid-Lift

Rear Suspension Air

WINDSCREEN WIPERS INOP SLIDING 5TH WHEEL

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Drivers airbag
- Cruise control
- Central locking
- Air conditioning
- Leather seat trim
- Front electric windows


Photos







Condition Check



Damage Photos



1: Handle Outer nsf
Broken
Replace



2: Panel Front
Dented
With Paint Damage



3: Qtr Panel osr
 Scratched
 Over 25mm Not Thru Paint

Interior

Carpet Condition		Upholstery Condition	
Seat Condition	Average	Odour	Average
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK