

VEHICLE INSPECTION REPORT

PJ66AZG

Daf LF 150

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 19/10/2016

VIN XLRAEL1500L458924

Axle Combi 4x2

Year 2016

Body Style Box Van

Rear Suspension Steel

Mileage 815,746 Km Warranted

MOT Due 31/01/2027

Tail Lift Cantilever

Fuel Type Diesel

Cab Type DAY CAB

Colour RED

Gearbox MANUAL

COLLECTED AS NON-RUNNER, ENGINE FAILURE/ ENGINE MISFIRE, WARNING LIGHT ON DASH

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3





OSO4

Features

- Cruise control
- Radio/CD
- Front electric windows
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Number Plate Front
Broken
Replace



3: Bumper Front
Dented
With Paint Damage

4: Panel Front
Scratched
Over 25mm Thru Paint



5: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint

6: Qtr Panel osr
Scratched
Over 25mm Thru Paint



7: Door osf
Scratched
Over 25mm Not Thru Paint

8: Door osf
Scratched
Over 25mm Thru Paint



9: Dash Warning Lights
Displayed
No Action

10: Door Pad osf
Soiled
Heavy



11: Seat Base Cover nsf
Holed
Over 3mm

Interior

Carpet Condition	OK	Upholstery Condition	Poor
Seat Condition	Poor	Odour	-
Engine Runs	Fault	No Excessive Smoking	OK
EML light illuminated	Fault	DPF light illuminated	OK
ABS light illuminated	OK		