

VEHICLE INSPECTION REPORT

MJ67YMK

Daf CF 230

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date	02/02/2018	Colour	RED	Cab Type	SLEEPER CAB
Year	2018	VIN	XLRAEM3700G165938	Gearbox	MANUAL
Mileage	586,968 Km Warranted	Body Style	Flatbed	Axle Combi	4x2
Fuel Type	Diesel	MOT Due	30/04/2026	Rear Suspension	Air

SERVICE SCHEDULE LIST AVAILABLE

Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Cruise control
- Digital radio
- Front electric windows
- Central locking
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Panel Front
Cracked
Replace

4: Panel Front
Scratched
Over 25mm Thru Paint



5: Door nsf
Dented
With Paint Damage



6: Door nsf
Dented
With Paint Damage



7: Door nsf
Dented
With Paint Damage

8: Door Mirror Assy nsf
Broken
Replace



9: Bumper Front Moulding
Broken
Replace



10: Wing nsf
Scratched
Over 25mm Thru Paint



11: Qtr Panel osr
Scratched
Over 25mm Thru Paint



12: Wing osf
Cracked
Replace



13: Seat Base Cover osf
Holed
Over 3mm



14: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		