

VEHICLE INSPECTION REPORT

ND730KO

Carr Hill Doncaster

Renault Trafic SL30 EXTRA Blue DCI 150PS

Inspection		Vehicle			
Serious Damage?	No	VAT	Plus VAT		
		V5	Present	- -	
Details					
Reg. date	10/11/2023	VIN	VF1FL000271634706	CAP Below	£14,750.00
Year	2023	Body Style	Panel Van SWB	Gearbox	AUTOMATIC
Mileage	28,952 Miles Not Warranted	MOT Due	09/11/2026	Gears	6
		CAP Clean	£17,800.00	Axle Combi	4x2
Fuel Type	Diesel	CAP Average	£16,800.00		
Colour	WHITE		•	-	

A/C, SINGLE SIDE DOOR, REAR SENSORS, E/WINDOWS & MIRRORS *WARNING LIGHTS ON DASH, ONLY RUNS WITH JUMP PACK ATTACHED*

Tyres			
Tyres NSF			
NSR			
OSF		,	
OSR			
Spare			

Photos


















Condition Check



Damage Photos



1: Bumper Front Moulding Scuffed (Unpainted) UpTo 100mm



2: Bumper Rear Scratched Over 25mm Not Thru Paint



3: Qtr Panel osr Scratched Over 25mm Thru Paint



4: Bumper Rear Moulding Scuffed (Unpainted) Over 100mm



5: General Exterior Soiled Light



6: Sill os Dented Over 30mm



Interior

Carpet Condition Seat Condition	Average Average		Upholstery Condition Odour	Average No	
Engine Runs		Fault	Gearbox 1st and Revers	se Test	OK
Brakes		OK	Clutch Slip Test from Sta	atic	OK
Turbo Boosting		Fault	Gearbox Static Gear Se	lection (engine running)	OK
Parking Brake		ОК	No Excessive Smoking		OK
EML light illuminated		OK	Oil warning light illumina	ated	OK
Airbag light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK	Service indicator light illu	uminated	OK