

VEHICLE INSPECTION REPORT

YG17HVX

Daf LF 230

Inspection

Vehicle

VAT	Plus VAT
V5	To Follow

Details

Reg. date	13/06/2017	Colour	BLUE	Cab Type	DAY CAB
Year	2017	VIN	XLRAEL3700L459406	Gearbox	MANUAL
Mileage	187,880 Km Warranted	Body Style	Dropside & Crane	Axle Combi	4x2
Fuel Type	Diesel	MOT Due	30/04/2026	Rear Suspension	Steel

WARNING LIGHT ON DASH SERVICE SCHEDULE LIST AVAILABLE, REAR HMF 1420K REMOTE CRANE (YEAR 2017) & BLOCK GRAB, SURROUND CAMERA SYSTEM *NO BATTERIES FOR CRANE REMOTE*


Tyres




NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Park assist camera


Photos








Condition Check



Damage Photos



1: Wing osf
Scratched
Over 25mm Thru Paint

2: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



3: Bonnet
Chipped
Multiple Chips



4: Wings
Scratched
Over 25mm Thru Paint



5: Bumper Front
Dented
Between 10mm + 30mm



6: Other
N/A
N/A



7: Other
N/A
N/A

8: Other
N/A
N/A



9: Other
N/A
N/A



10: Door osf
Scratched
Over 25mm Thru Paint



11: Wing osf
Scratched
Over 25mm Thru Paint

12: Seat Base Cover osf
Holed
Over 3mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK