

VEHICLE INSPECTION REPORT

PE65VDK

Daf LF 150

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 29/10/2015

VIN XLRAEL1500L448561

Axle Combi 4x2

Year 2015

Body Style Box Van

Rear Suspension Steel

Mileage 549,058 Km Warranted

MOT Due 30/09/2026

Tail Lift Cantilever

Fuel Type Diesel

Cab Type DAY CAB

Colour RED

Gearbox MANUAL

WARNING LIGHT ON DASH

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1



OSO2

OSO3


OSO4

Photos





Condition Check



Damage Photos



1: Wing osf
Scratched
Over 25mm Not Thru Paint



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Bonnet
Scratched
Over 25mm Thru Paint

4: Screen Front
Chipped
Over 10mm



5: Bumper Front
Scratched
25 to 100mm Thru Paint

6: Other
N/A
N/A



7: Door Mirror Assy nsf
Broken
Replace

8: Other
N/A
N/A



9: Bumper Rear
Rusted
Over 5mm

10: Other
N/A
N/A



11: Other
N/A
N/A

12: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm



13: Door osf
Scratched
Over 25mm Not Thru Paint

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK