

VEHICLE INSPECTION REPORT

AP72WAE

Ssangyong Musso 2.2TD 202PS SARACEN

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 Buyer To Apply

Details

Reg. date	03/11/2022	VIN	KPAYA1EESNP183321	CAP Below	£10,200.00
Year	2022	Body Style	Pickup Double Cab	Gearbox	AUTOMATIC
Mileage	57,748 Miles Not Warranted	MOT Due	02/11/2026	Gears	6
Fuel Type	Diesel	CAP Clean	£13,350.00	Axle Combi	4x4
Colour	WHITE	CAP Average	£12,150.00		

REAR PANEL WINDOW MISSING AD-BLUE, TOW BAR, E/MIRRORS

Tyres

NSF

NSR

OSF

OSR







Spare

Features

- Bluetooth connection
- Rear parking sensor
- Passenger airbag
- Front parking sensor
- Air conditioning
- Central locking
- Navigation system
- Front electric windows
- Leather seat trim
- Park assist camera
- Drivers airbag


Photos







Condition Check



Damage Photos



1: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm

2: Screen Rear
Missing
Replace



3: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		No
Engine Runs		OK	Gearbox 1st and Reverse Test		OK
Brakes		OK	Clutch Slip Test from Static		OK
Parking Brake		OK	Gearbox Static Gear Selection (engine running)		OK
			No Excessive Smoking		OK
EML light illuminated		OK	Oil warning light illuminated		OK
Airbag light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK	Service indicator light illuminated		OK