

VEHICLE INSPECTION REPORT

713385

LIU-GONG 917F

Inspection

Vehicle

VAT	Plus VAT
V5	N/A

Details

Reg. date		Fuel Type	Diesel	Body Style	Material Handler
Year	2023	Colour		Gearbox	Hydrostatic
Mileage	47 Hours Warranted	VIN			

UNUSED TRACKED, ELEVATED CAB, PIPED, CUMMINS ENGINE

Tyres

NSF

NSR

OSF

OSR

Spare

Photos



