

VEHICLE INSPECTION REPORT

PE63NLN

Daf LF 45.140

Non Runner

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 19/11/2013

VIN XLRAE45FF0L432690

Gearbox MANUAL

Year 2013

Body Style Box Van

Axle Combi 4x2

Mileage 819,292 Km Warranted

Service history Yes

Rear Suspension Steel

Fuel Type Diesel

MOT Due 28/02/2026

Tail Lift Column

Colour RED

Cab Type DAY CAB


Tyres






NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Cruise control
- Cloth seat trim
- Radio/CD
- Front electric windows
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Grille Front
Broken
Replace



3: Bumper Front
Dented
Over 30mm



4: Moulding nsf Wing
Broken
Replace



5: Moulding nsf Wing
Broken
Replace



6: Other
N/A
N/A



7: Door osf
Chipped
Multiple Chips



8: Door Mirror Assy osf
Broken
Replace





9: Carpets Front
Holed
Over 3mm

Interior

Carpet Condition	Poor	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		