

VEHICLE INSPECTION REPORT

PF67WZY

Iveco Daily 35-140

Non Runner

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 21/02/2018

Year 2018

Mileage 167,659 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN ZCFCC35A10D595272

Body Style Dropside

MOT Due 13/03/2026

CAP Clean £5,150.00

CAP Average £4,400.00

CAP Below £3,325.00

Gearbox MANUAL

Gears 6

NON-RUNNER, POWERS UP DOES NOT CRANK, ENGINE REQUIRES ATTN 3450WB

Tyres

NSF

NSR

OSF


OSR

Spare

Features


- Front electric windows

Photos





Condition Check



Damage Photos



1: Wing osf
Dented
With Paint Damage

2: Bonnet
Dented
With Paint Damage



3: Other
N/A
N/A

4: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



5: Wing nsf
Dented
With Paint Damage

6: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



7: Other
N/A
N/A

8: Seat Base Cover osf
Holed
Over 3mm





9: Other
N/A
N/A

10: Other
N/A
N/A



11: Other
N/A
N/A

12: Door osf
Dented
With Paint Damage



13: Door Mirror Assy osf
Broken
Replace

14: Door osf
Scratched
Over 25mm Thru Paint




15: Seat Base Cover osf
Holed
Over 3mm

16: Other
N/A
N/A



17: Other
N/A
N/A

18: Other
N/A
N/A



19: Seat Back Cover nsf
Burn
Over 3mm

Interior

Carpet Condition	Poor	Upholstery Condition	Poor
Seat Condition	Poor	Odour	No
Engine Runs	Fault		