

VEHICLE INSPECTION REPORT

PE17HRZ

Daf CF 440

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 13/03/2017

Year 2017

Mileage 1,444,630 Km
Warranted

Fuel Type Diesel

Colour RED

VIN XLRTGM4100G150429

Body Style Tractor Unit

Service history Yes

Service documents Printout

MOT Due Expired

Cab Type SLEEPER CAB

Gearbox AUTOMATIC

Axle Combi 6x2

Steering Combi Mid-Lift

Rear Suspension Air

COLLECTED AS NON-RUNNER, CORROSION, TYRES, AIRTANKS, DISCS AND PADS REQ ATTN, INPUT ERROR ON MOT

Tyres





NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Cruise control
- Central locking
- Radio/CD
- Cloth seat trim
- Air conditioning
- Front electric windows


Photos







Condition Check




Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Chipped
Multiple Chips



3: Door nsf
Dented
With Paint Damage

4: Door nsf
Dented
Over 30mm



5: Wing nsf
Cracked
Replace

6: Qtr Panel Trim os
Scuffed
Over 25mm



7: Door osf
Dented
With Paint Damage

8: Door osf
Scratched
Over 25mm Not Thru Paint



9: Carpets Front
Missing
Replace

10: Seat Base Cover nsf
Holed
Over 3mm

Interior

Carpet Condition		Poor	Upholstery Condition		OK
Seat Condition		Poor	Odour		-
Engine Runs		OK	No Excessive Smoking		OK
EML light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK			