

VEHICLE INSPECTION REPORT

C318077

CARTWRIGHT CURTAINSIDE

Inspection

Vehicle

VAT	Plus VAT
V5	N/A

Details

Reg. date	01/01/2011	Colour	WHITE	Brakes	Disc
Year	2011	VIN	110648	Axle Combi	Tri
Mileage	Not Showing	Body Style	Trailer	Rear Suspension	Air
Fuel Type		MOT Due	30/04/2026	Rear Doors	Roller

MERCEDES AXLES, RAISE & LOWER VALVE, FERRY LASHING RINGS, ENXL RATED BODY

Tyres

NSF

NSR

OSF

OSR

Spare

Photos



