

VEHICLE INSPECTION REPORT

LN67WSJ

Carr Hill

Ford Transit 350 2.0 TDCI 130PS

Inspection		Vehicle			
Serious Damage?	No	VAT	Plus VAT		
		V5	Present		
Details					
Reg. date	30/09/2017	VIN	WF0XXXTTGXHB72608	CAP Below	£2,875.00
Year	2017	Body Style	Panel Van LWB	Gearbox	MANUAL
Mileage	110,087 Miles Warranted	MOT Due	04/07/2025	Gears	6
		CAP Clean	£4,475.00		
Fuel Type	Diesel	CAP Average	£3,775.00		
Colour	GREEN	<u></u>	,		

SIDE LOADING DOOR, REAR VIEW CAMERA, E/WINDOWS

	•	·		
Tyres				
Tyres NSF				
NSR				
OSF				
OSR				
Spare				

Photos

















Condition Check



Damage Photos



1: Screen Front Chipped UpTo 10mm



2: Screen Front Chipped UpTo 10mm



3: Bonnet Chipped Multiple Chips



4: Panel Rear Scratched UpTo 25mm Thru Paint



5: Seat Back Cover osf Torn Over 3mm

Interior

Carpet Condition Seat Condition	OK Poor		Jpholstery Condition OK Odour No	
EML light illuminated		OK	Oil warning light illuminated	OK
Airbag light illuminated		OK	DPF light illuminated	OK
ABS light illuminated		OK	Service indicator light illuminated	OK