

VEHICLE INSPECTION REPORT

PK67VFX

Daf CF 450

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 09/11/2017

Year 2017

Mileage 1,099,556 Km
Warranted

Fuel Type Diesel

Colour RED

VIN XLRTGM4100G181308

Body Style Tractor Unit

MOT Due 30/06/2026

Cab Type SLEEPER CAB

Gearbox AUTOMATIC

Axle Combi 6x2

Steering Combi Mid-Lift

Rear Suspension Air

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2


OSO3



OSO4

Features


- Air conditioning

Photos





Condition Check



Damage Photos



1: Wing osf
Scratched
Over 25mm Thru Paint



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Other
N/A
N/A

4: Bonnet
Chipped
Multiple Chips



5: Screen Front
Chipped
UpTo 10mm

6: Other
N/A
N/A



7: Wing nsf
Cracked
Replace

8: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



9: Door nsf
Dented
With Paint Damage

10: Other
N/A
N/A



11: Door osf
Scratched
Over 25mm Not Thru Paint

12: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm



13: Other
N/A
N/A

14: Carpets Front
Holed
Over 3mm



15: Door Pad osf
Broken
Replace

Interior

Carpet Condition		Average		Upholstery Condition		Average	
Seat Condition		Average		Odour		-	
Engine Runs		OK		Gearbox 1st and Reverse Test		OK	
Brakes		OK		Clutch Slip Test from Static		OK	
Parking Brake		OK		Gearbox Static Gear Selection (engine running)		OK	
				No Excessive Smoking		OK	
EML light illuminated		OK		Oil warning light illuminated		OK	
Airbag light illuminated		OK		DPF light illuminated		OK	
ABS light illuminated		OK		Service indicator light illuminated		OK	