

VEHICLE INSPECTION REPORT

PF66KJZ

Daf CF 440

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 23/11/2016

Year 2016

Mileage 1,566,684 Km
Warranted

Fuel Type Diesel

Colour RED

VIN XLRTGM4100G134534

Body Style Tractor Unit

Service history Yes

Service documents Printout

MOT Due 31/07/2026

Cab Type SLEEPER CAB

Gearbox AUTOMATIC

Axle Combi 6x2

Steering Combi Mid-Lift Steer

Rear Suspension Air

COLLECTED AS NON-RUNNER

Tyres

NSF NSI1 NSI2 NSI3 NSI4

OSF OSI1 OSI2 OSI3 OSI4


Spare NSO1 NSO2 NSO3 NSO4

OSO1 OSO2 OSO3 OSO4

Features

- Cruise control
- Central locking
- Radio/CD
- Cloth seat trim
- Air conditioning
- Front electric windows


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Bumper Front
Dented
Over 30mm

4: Door nsf
Chipped
Multiple Chips



5: Door osf
Chipped
Multiple Chips

6: Door osf
Scratched
Over 25mm Thru Paint



7: Seat Base Cover nsf
Holed
Over 3mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		