

# VEHICLE INSPECTION REPORT

**PK67VGD**

## Daf CF 450

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Present

### Details

Reg. date 06/11/2017

Year 2017

Mileage 1,017,909 Km  
Warranted

Fuel Type Diesel

Colour RED

VIN XLRTGM4100G181081

Body Style Tractor Unit

MOT Due 31/08/2026

Cab Type SLEEPER CAB

Gearbox AUTOMATIC

Axle Combi 6x2

### Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3

OSO4





## Features


- Air conditioning

## Photos












## Condition Check



## Damage Photos



1: Wing osf  
Chipped  
Multiple Chips



2: Bumper Front  
Chipped  
Multiple Chips



3: Bonnet  
Chipped  
Multiple Chips

4: Wing nsf  
Chipped  
Multiple Chips



5: Other  
N/A  
N/A

6: Other  
N/A  
N/A



7: Door Mirror Assy nsf  
Scuffed (Unpainted)  
Over 100mm

8: Door nsf  
Scratched  
Over 25mm Thru Paint



9: Other  
N/A  
N/A

10: Door Mirror Assy osf  
Scuffed (Unpainted)  
Over 100mm



11: Other  
N/A  
N/A

## Interior

| Carpet Condition         | Average |  | Upholstery Condition                           | Average |
|--------------------------|---------|--|------------------------------------------------|---------|
| Seat Condition           | Average |  | Odour                                          | -       |
| Engine Runs              | OK      |  | Gearbox 1st and Reverse Test                   | OK      |
| Brakes                   | OK      |  | Clutch Slip Test from Static                   | OK      |
| Parking Brake            | OK      |  | Gearbox Static Gear Selection (engine running) | OK      |
|                          |         |  | No Excessive Smoking                           | OK      |
| EML light illuminated    | OK      |  | Oil warning light illuminated                  | OK      |
| Airbag light illuminated | OK      |  | DPF light illuminated                          | OK      |
| ABS light illuminated    | OK      |  | Service indicator light illuminated            | OK      |