

VEHICLE INSPECTION REPORT

PK67VGE

Daf CF 450

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 06/11/2017

VIN XLRTGM4100G181067

Axle Combi 6x2

Year 2017

Body Style Tractor Unit

Steering Combi Mid-Lift

Mileage 869,743 Km Warranted

MOT Due 31/07/2026

Rear Suspension Air

Fuel Type Diesel

Cab Type SLEEPER CAB

Colour RED

Gearbox AUTOMATIC

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3






OSO4

Features


- Air conditioning

Photos





Condition Check



Damage Photos



1: Wing osf
Chipped
Multiple Chips

2: Other
N/A
N/A



3: Bumper Front
Chipped
Multiple Chips



4: Bonnet
Chipped
Multiple Chips



5: Bumper Front
Scratched
25 to 100mm Thru Paint



6: Wing nsf
Chipped
Multiple Chips



7: Other
N/A
N/A

8: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm



9: Other
N/A
N/A

10: Other
N/A
N/A

Interior

Carpet Condition		Average		Upholstery Condition		Average	
Seat Condition		Average		Odour		-	
Engine Runs	OK			Gearbox 1st and Reverse Test	OK		
Brakes	OK			Clutch Slip Test from Static	OK		
Parking Brake	OK			Gearbox Static Gear Selection (engine running)	OK		
				No Excessive Smoking	OK		
EML light illuminated	OK			Oil warning light illuminated	OK		
Airbag light illuminated	OK			DPF light illuminated	OK		
ABS light illuminated	OK			Service indicator light illuminated	OK		