

VEHICLE INSPECTION REPORT

C356020

DON BUR BOX

Inspection

Vehicle

VAT	Plus VAT
V5	N/A

Details

Reg. date	01/01/2013	VIN	SEPBV38GKDL061885	Brakes	Disc
Year	2013	Body Style	Trailer	Axle Combi	Tri
Mileage	TBC	Service history	Yes	Rear Suspension	Air
Fuel Type		Service documents	Printout	Rear Doors	Roller
Colour	RED	MOT Due	30/11/2025		

REAR FRAME CRACKED BPW AXLES, RAISE & LOWER VALVE, FERRY LASHING RINGS

Tyres

NSF
NSR
OSF
OSR
Spare

Photos



