

VEHICLE INSPECTION REPORT

PK67VGM

Daf CF 450

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 09/11/2017

Year 2017

Mileage 1,037,330 Km
Warranted

Fuel Type Diesel

Colour RED

VIN XLRTGM4100G181761

Body Style Tractor Unit

MOT Due 28/02/2026

Cab Type SLEEPER CAB

Gearbox AUTOMATIC

Axle Combi 6x2

Steering Combi Mid-Lift

Rear Suspension Air

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2


OSO3


OSO4

Features


- Air conditioning

Photos





Condition Check



Damage Photos



1: Wing osf
Chipped
Multiple Chips



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Bonnet
Chipped
Multiple Chips



4: Bumper Front
Dented
Between 10mm + 30mm



5: Wing nsf
Cracked
Replace



6: Door osf
Chipped
1 To 5



7: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm

8: Other
N/A
N/A



9: Other
N/A
N/A

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs		OK	Gearbox 1st and Reverse Test		OK
Brakes		OK	Clutch Slip Test from Static		OK
Parking Brake		OK	Gearbox Static Gear Selection (engine running)		OK
			No Excessive Smoking		OK
EML light illuminated		OK	Oil warning light illuminated		OK
Airbag light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK	Service indicator light illuminated		OK