

VEHICLE INSPECTION REPORT

PK67VHY

Daf CF 450

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 14/11/2017

Year 2017

Mileage 1,174,108 Km
Warranted

Fuel Type Diesel

Colour RED

VIN XLRTGM4100G182439

Body Style Tractor Unit

MOT Due 31/07/2026

Cab Type SLEEPER CAB

Gearbox AUTOMATIC

Axle Combi 6x2

Steering Combi Mid-Lift

Rear Suspension Air

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2


OSO3

OSO4


Features

- Air conditioning


Photos







Condition Check



Damage Photos



1: Wing osf
Scratched
Over 25mm Thru Paint

2: Other
N/A
N/A



3: Bumper Front
Chipped
Multiple Chips



4: Bumper Front
Dented
With Paint Damage



5: Wing nsf
Chipped
Multiple Chips



6: Other
N/A
N/A



7: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



8: Door nsf
Scratched
Over 25mm Not Thru Paint






9: Other
N/A
N/A

10: Other
N/A
N/A



11: Door osf
Scratched
UpTo 25mm Thru Paint

12: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm



13: Seat Back Cover osf
Holed
Over 3mm

14: Other
N/A
N/A

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK	
			No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	