

VEHICLE INSPECTION REPORT

DX17ZRT

Daf XF 460

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 Buyer To Apply

Details

Reg. date	01/04/2017	Colour	WHITE	Gearbox	AUTOMATIC
Year	2017	VIN	XLRTGH4300G152208	Axle Combi	6x2
Mileage	983,132 Km Not Warranted	Body Style	Tractor Unit	Steering Combi	Mid-Lift
Fuel Type	Diesel	Cab Type	SPACE CAB	Rear Suspension	Air

WARNING LIGHT ON DASH SLIDING 5TH WHEEL, SURROUND CAMERA SYSTEM

Tyres








NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Cruise control
- Park assist camera
- Radio/CD
- Air conditioning
- Front electric windows
- Rear electric windows
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Bumper Front
Chipped
Multiple Chips



3: Bumper Front Moulding
Broken
Replace

4: Moulding nsf Wing
Broken
Replace



5: Door nsf
Scratched
Over 25mm Thru Paint

6: Door Mirror Assy nsf
Broken
Replace



7: Qtr Panel nsr
Chipped
Over 5mm

8: Qtr Panel Moulding ns
Broken
Replace



9: Wheel Trim osr
Broken
Replace

10: Wheel Trim osr
Broken
Replace



11: Qtr Panel Moulding os
Broken
Replace

12: Panel Rear
Rusted
Over 5mm



13: Panel Front
Rusted
Over 5mm

14: Door osf
Chipped
Multiple Chips



15: Screen Front
Chipped
Over 10mm

16: Roof
Rusted
Over 5mm



17: Carpets Front
Holed
Over 3mm

18: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	Poor		Upholstery Condition	OK
Seat Condition	OK		Odour	-
Engine Runs	OK		No Excessive Smoking	OK
EML light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK			