

VEHICLE INSPECTION REPORT

LM66MWU

Ford Transit Courier 1.5 TDCI

Non Runner
Inspection

Serious Damage?		Vehicle	
No		VAT	Plus VAT
		V5	Present

Details

Reg. date	18/11/2016	VIN	WF0WXXTACWGL62362	CAP Below	£1,275.00
Year	2016	Body Style	Panel Van SWB	Gearbox	MANUAL
Mileage	140,173 Miles Warranted	MOT Due	30/06/2025	Gears	5
Fuel Type	Diesel	CAP Clean	£2,050.00		
Colour	GREEN	CAP Average	£1,725.00		

NON RUNNER-POWERS UP DOES NOT CRANK
SIDE LOADING DOOR

Tyres


NSF
NSR
OSF
OSR
Spare

Photos





Condition Check



Damage Photos



1: Bumper Front Moulding
Scratched (Painted)
Over 25mm Thru Paint



2: Bumper Front Moulding
Scratched (Painted)
Over 25mm Thru Paint



3: Screen Front
Chipped
Over 10mm



4: Wing nsf
Dented
With Paint Damage



5: A Post ns
Dented
With Paint Damage



6: Door nsr
Scratched
Over 25mm Thru Paint



7: General Exterior
Soiled
Light



8: Qtr Panel osr
Scratched
Over 25mm Thru Paint



9: Qtr Panel osr
Scratched
Over 25mm Thru Paint



10: Door osf
Scratched
Over 25mm Thru Paint



11: Carpets Front
Holed
Over 3mm

Interior

Carpet Condition		Upholstery Condition	
Seat Condition	Average	Odour	Average
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK