

VEHICLE INSPECTION REPORT

PF14TZS

Daf LF 150

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date	27/08/2014	VIN	XLRAEL1500L438118	Cab Type	DAY CAB
Year	2014	Body Style	Box Van	Gearbox	MANUAL
Mileage	835,782 Km Warranted	Service history	Yes	Axle Combi	4x2
Fuel Type	Diesel	Service documents	Printout	Rear Suspension	Steel
Colour	RED	MOT Due	31/07/2026	Tail Lift	Cantilever

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Cruise control
- Cloth seat trim
- Radio/CD
- Front electric windows
- Central locking


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Door Mirror Assy nsf
Broken
Replace

4: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



5: Qtr Panel osr
Scratched
Over 25mm Thru Paint

6: Door osf
Scratched
Over 25mm Thru Paint



7: Door Pad osf
Soiled
Heavy

8: Seat Base Cover osf
Holed
Over 3mm



9: Fascia Panel
 Holed
 Over 3mm

10: Seat Base Cover nsf
 Holed
 Over 3mm

Interior

Carpet Condition	OK	Upholstery Condition	Poor
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		