

VEHICLE INSPECTION REPORT

YN70ORL

Ford Transit 350 2.0 ECOBLUE 130PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 21/09/2020

Year 2020

Mileage 100,357 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN WF0EXXTTREL37048

Body Style Panel Van L2

MOT Due 03/10/2026

CAP Clean £7,400.00

CAP Average £6,500.00

CAP Below £5,200.00

Gearbox MANUAL

Gears 6

ENGINE RATTLE AD-BLUE, SIDE LOAD DOOR, TOW BAR

Tyres

NSF

NSR

OSF


OSR


Spare

Features


- Bluetooth connection
- Digital radio
- Passenger airbag
- Front parking sensor
- USB/iPod interface
- Central locking
- Park assist camera
- Front electric windows
- Cloth seat trim
- Rear parking sensor
- Drivers airbag

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Bonnet
Scratched
Over 25mm Thru Paint



3: Wing Front Arch Extension ns
Broken
Replace



4: Door nsf
Dented
Between 10mm + 30mm



5: Aperture Seal nsf
Broken
Replace



6: Fuel Flap
Missing
Replace



7: Qtr Panel nsr
Dented
Over 30mm

8: Qtr Panel nsr
Dented
With Paint Damage



9: Door nsf
Dented
Over 30mm



10: Qtr Panel nsr
Cracked
Replace



11: Sill ns
Scratched
Over 25mm Thru Paint



12: Panel Rear
Scratched
Over 25mm Thru Paint



13: Qtr Panel nsr
Dented
With Paint Damage



14: Bumper Rear
Cracked
Over 25mm



15: Lamp nsr
Broken
Replace

16: Door nsr
Dented
Over 30mm



17: Door osr
Dented
Over 30mm

18: Door osr
Rusted
Over 5mm



19: Panel Rear
Dented
Over 30mm

20: Qtr Panel Trim os
Broken
Replace



21: Qtr Panel Trim os
Broken
Replace

22: Door osf
Chipped
Multiple Chips



23: Door osf
Dented
Over 30mm

24: Panel Front
Scratched
Over 25mm Thru Paint



25: Carpets Front
Holed
Over 3mm

26: Seat Base Cover nsf
Soiled
Heavy



27: Centre Console Front
 Holed
 Over 3mm

28: Dash Warning Lights
 Displayed
 No Action

Interior

Carpet Condition		Average	Upholstery Condition		OK
Seat Condition		Average	Odour		Yes
Engine Runs		OK	No Excessive Smoking		OK
EML light illuminated		OK	Oil warning light illuminated		OK
ABS light illuminated		OK	DPF light illuminated		OK
			Service indicator light illuminated		OK
Windows		OK	Radio		OK
			Steering		OK